

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090437/KPA3Q2

Date: 06/01/2025

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0003714_04
Claimant Vehicle No :	SLC3714X	Insured Vehicle No :	PC6088C
Date of Loss:	18/09/2024	Nature of Claim:	TP
		Claim No:	MFL2024D0011033

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC3714X	Engine No:	2AR1260621
Make & Model:	TOYOTA VELLFIRE, 2.5 Z G-EDITION CVT (A)	Chassis No:	AGH300008477
Reg. Date:	12/05/2016 (Man. Year: 2015)	Odometer:	115831 km
Colour:	Metallic Pearl White		
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50Z R18	Rear Tyre Size:	235/50Z R18
Front Left Side:	APLUS 6 mm	Rear Left Side:	APLUS 7 mm
Front Right Side:	APLUS 6 mm	Rear Right Side:	APLUS 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,524.00	836.00	688.00	45.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	540.00	140.00	400.00	74.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	2,064.00	976.00	1,088.00	52.71
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	24/09/2024	
Date Inspected:	24/09/2024	Inspected At: Ding Auto Pte Ltd (HQ) 176 Sin Ming Drive #04-06, Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2025)
<b>Parts:</b>	M1-MPV	TOYOTA VELLFIRE 2.5 Z G-EDITION CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLC3714X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR RHS (WCP)	Cracked	640.00 F	*640.00 F
2	1		*SIDE MIRROR LOWER COVER RHS (WCP)	*Check	60.00 F	*- F
3	1		*FRONT FENDER RHS (WCP)	Serviceable	425.00 F	*- F
4	1		*SIDE MIRROR COVER RHS (WCP)	Missing	60.00 F	*60.00 F
5	1		*SIDE MIRROR GLASS (WCP)	Serviceable	95.00 F	*- F
6	1		*SIDE MIRROR SIGNAL LIGHT BAR (WCP)	Cracked	60.00 F	*60.00 F
7	1		*FRONT FENDER INNER SHIELD CLIP	Not Necessary	50.00 FS	*- FS
					<b>Sub Total (S\$)</b>	<b>1,390.00 760.00</b>
					<b>+ Margin on L,N Items 10.00/10.00% (S\$)</b>	<b>134.00 76.00</b>
					<b>Total Parts (S\$)</b>	<b>1,524.00 836.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING FRONT FENDER RHS ,SIDE MIRROR COVER RHS	New	400.00	80.00
2	REMOVE AND REFIT SIDE MIRROR RHS	New	60.00	60.00
3	REMOVE AND REFIT FRONT FENDER RHS	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>540.00</b>	<b>140.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >