

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24060018/ENP3E2

Date: 12/07/2024

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SNB481T	Insured Vehicle No :	SKK21B
Date of Loss:	05/06/2024	Nature of Claim:	TP
		Claim No:	DMPC2400713H/02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB481T		
Make & Model:	AUDI A5, 2.0 SPORTBACK TFSI S TRONIC (A)	Engine No:	DEM038684
Reg. Date:	28/02/2023 (Man. Year: 2022)	Chassis No:	WAUZZZF53PA004033
Colour:	Black	Odometer:	18063 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/30Z R20	Rear Tyre Size:	265/30Z R20
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,958.40	3,345.30	21,613.10	86.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	690.00	3,640.00	84.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,288.40	4,035.30	25,253.10	86.22
Approved Total (Overridden) (S\$)		3,250.00		
(S\$)	29,288.40	3,250.00	26,038.40	88.90
+ GST 9.00/9.00% (S\$)	2,635.96	292.50	2,343.46	88.90
Nett Amount (S\$)	31,924.36	3,542.50	28,381.86	88.90

INSPECTION

Date of Assignment:	10/06/2024	
Date Inspected:	10/06/2024	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jul 2024)
Parts:	143	AUDI A5 2.0 SPORTBACK TFSI S TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB481T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	4,586.00 FL	*- FL
2	1		*BOOTLID CENTRE EMBLEM	Not Necessary	136.00 FL	*- FL
3	1		*BOOTLID A5 EMBLEM	Not Necessary	78.00 FL	*- FL
4	1		*BOOTLID RH LAMP ASSY	Not Necessary	1,276.00 FL	*- FL
5	1		*BOOTLID LH LAMP ASSY	Not Necessary	1,276.00 FL	*- FL
6	1		*BOOTLID LOCK	Not Necessary	323.00 FL	*- FL
7	1		*BOOTLID LOCK CATCH	Not Necessary	59.00 FL	*- FL
8	1		*BOOTLID WEATHERSTRIP	Not Necessary	378.00 FL	*- FL
9	1		*REAR BUMPER	Broken	2,945.00 FL	*2,945.00 FL
10	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FL	*30.00 FL
11	1		*REAR BUMPER LOWER GARNISH	Broken	310.00 FL	*310.00 FL
12	1		*REAR BUMPER RH REFLECTOR	Not Necessary	59.00 FL	*- FL
13	1		*REAR BUMPER LH REFLECTOR	Not Necessary	59.00 FL	*- FL
14	1		*REAR BUMPER RH EXHAUST CHROME	Not Necessary	432.00 FL	*- FL
15	1		*REAR BUMPER LH EXHAUST CHROME	Cut	432.00 FL	*432.00 FL
16	1		*REAR BUMPER RH SIDE REVERSE SENSOR	Not Necessary	233.00 FL	*- FL
17	1		*REAR BUMPER RH CENTRE REVERSE SENSOR	Not Necessary	233.00 FL	*- FL
18	1		*REAR BUMPER LH CENTRE REVERSE SENSOR	Not Necessary	233.00 FL	*- FL
19	1		*REAR BUMPER LH SIDE REVERSE SENSOR	Not Necessary	233.00 FL	*- FL
20	1		*REAR BUMPER REVERSE SENSOR HOLDERS	Not Necessary	120.00 FL	*- FL
21	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	512.00 FL	*- FL
22	1		*REAR BUMPER CENTRE BRACKET	Not Necessary	43.00 FL	*- FL
23	1		*REAR BUMPER RH SIDE BRACKET	Not Necessary	76.00 FL	*- FL
24	1		*REAR BUMPER LH SIDE BRACKET	Not Necessary	76.00 FL	*- FL
25	1		*REAR BUMPER REINFORCEMENT	Not Necessary	896.00 FL	*- FL
26	1		*RH TAILLAMP ASSY	Not Necessary	1,427.00 FL	*- FL
27	1		*RH TAILLAMP PANEL	Not Necessary	289.00 FL	*- FL
28	1		*LH TAILLAMP ASSY	Not Necessary	1,427.00 FL	*- FL
29	1		*LH TAILLAMP PANEL	Not Necessary	289.00 FL	*- FL
30	1		*END PANEL (OUTER)	Not Necessary	730.00 FL	*- FL
31	1		*END PANEL (INNER)	Not Necessary	414.00 FL	*- FL
32	1		*END PANEL INNER GARNISH	Not Necessary	187.00 FL	*- FL
33	1		*SET END PANEL INNER GARNISH CLIPS	Not Necessary	70.00 FL	*- FL
34	1		*REAR SPARE TYRE COVER	Not Necessary	189.00 FL	*- FL
35	1		*REAR SPARE TYRE SPONGE	Not Necessary	89.00 FL	*- FL
36	1		*REAR SPARE TYRE TOP BOARD COVER	Not Necessary	563.00 FL	*- FL
37	1		*EXHAUST SILENCER RH	Not Necessary	1,802.00 FL	*- FL
38	1		*EXHAUST SILENCER CLAMP RH	Not Necessary	55.00 FL	*- FL
39	1		*EXHAUST SILENCER LH	Not Necessary	1,802.00 FL	*- FL
40	1		*EXHAUST SILENCER CLAMP LH	Not Necessary	55.00 FL	*- FL
41	1		*BOOTLID SPOILER	Not Necessary	1,550.00 FS	*- FS
42	1		*END PANEL JOINT SEALANT (OUTER)	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
43	1		*END PANEL JOINT SEALANT (INNER)	Not Necessary	80.00 FS	*- FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$)	26,182.00	3,717.00
					- List Item Discount on L Items 5.00/10.00% (\$)	1,223.60	371.70
					Total Parts (\$)	24,958.40	3,345.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,500.00	250.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	250.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	80.00	0.00
5	REMOVE AND REPLACE BOOTLID INNER MECHANISM TO NEW BOOTLID	New	120.00	0.00
6	REMOVE AND REFIT BOOTLID REVERSE CAMERA TO ASSIST REPAIR	New	100.00	0.00
7	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	30.00
8	REMOVE AND REPLACE REAR INNER TRIMS, GARNISH AND BOARDS TO ASSIST REPAIR	New	300.00	0.00
9	REMOVE AND REPLACE EXHAUST SILENCER, CLAMPS AND EXHAUST CHROME TO ASSIST REPAIR	New	450.00	50.00
10	CONDUCT DIAGNOSTIC CHECK AND RESET SYSTEM	New	400.00	80.00
Gross Labour Cost (\$)			4,330.00	690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >