

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sim, Priscilla-LK

Date: 28 Aug 2024

Preliminary Advice

Vehicle No	: SDA7818J	Accident Date	: 19/06/2024
Make	: AUDI A8 L	Policy No.	: 1900080269
Assignment Date	: 26/06/2024	Excess	: S\$0.00
Date of Inspection	: 25/06/2024	Est. Duration of Repair	: 0
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle caught fire.

Repairer's Estimate (Gross)	:S\$	442,321.00
Revised Amount	:S\$	Total loss
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	177,000.00
COE / PARF Rebate	:S\$	95,320.00
Salvage Value	:S\$	
Margin for Repair	:S\$	81,680.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (x) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Please be informed owner that the vehicle not economical for repair.