Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 AIG Building, 78 Shenton Way Paya Ubi Industrial Park #09-16 Singapore 079120 Singapore 408933

Attn: Sim. Priscilla-LK Date: 27 Jun 2024

Preliminary Advice

Vehicle No : SDA7818J Accident Date : 19/06/2024 Make : AUDI A8 L Policy No. : 1900080269 Assignment Date : 26/06/2024 Excess : S\$0.00 Date of Inspection : 25/06/2024 Est. Duration of Repair : 0

: PREMIUM AUTOMOBILES PTE LTD (UBI) Inspection At

> 55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

Pending investigation and SCDF fire report.

Repairer's Estimate (Gross)	:S\$	442,321.00
Revised Amount	:S\$	Total loss
Check Items (Estimated)	:S\$	
Total	:S\$	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ 200,000.00 COE / PARF Rebate :S\$ 95,320.00 Salvage Value :S\$

Margin for Repair :S\$ 104,680.00

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	dly
		let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. (x)

Other comments: Pending investigation. (X)

Please be informed owner that the vehicle not economical for repair.