

**AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.**

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)

Tel : 6702 1555 Fax : 6702 1444

Co. Reg No. : 201500047H GST No. : 201500047H

Email : st.sim@autobacs.com.sg

not full
in
max
25/9/24
1/c & 4/150
whp. Atkay-
6 days

TO	: LIBERTY INSURANCE (SMX3873Y)	DATE	: 24-Sep-24
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXX465D	P -	
		S -	
		L -	
VEHICLE DETAILS			
VEHICLE NO.	: SKD2213M	TOTAL	:
MODEL / MAKE	: VOLKSWAGEN GOLF	L/S -20%	:
CHASSIS NO.	: WVVZZZ1KZCW108795	SUB TOTAL	:
ACCIDENT DETAIL			
DATE	: 20-Sep-24		
TIME	: 12:00 HRS	CONTACT PERSON	: MR. SIM 9844 0974

QUOTATION SUMMARY PAGE 01**CLAIMS DETAIL : PARTS LIST**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER 1132.05 DUS	1	\$ 1,200.00	\$ 1,200.00
2	R/L TAILAMP INNER 290.45 CNA	1	\$ 380.00	\$ 380.00
3	R/L TAILAMP OUTER CNA	1	\$ 380.00	\$ 380.00
4	REAR TAILGATE R	1	\$ 2,500.00	\$ 2,500.00
5	R/L SIDE DOOR MIRROR BODY 11	1	\$ 700.00	\$ 700.00
6	REAR BUMPER LH REFLECTOR 56.75 CNA	1	\$ 80.00	\$ 80.00
7	REAR END PANEL 001201	1	\$ 700.00	\$ 700.00
8	R/R FENDER INNER LINER 12.1	1	\$ 190.00	\$ 190.00
9	REAR BUMPER REINFORCEMENT 606.05 BNF	1	\$ 650.00	\$ 650.00
TOTAL PRICE				\$ 6,780.00
LESS -10%				\$ (678.00)
SUB TOTAL PRICE				\$ 6,102.00

Rear bumper side holder HM 85.00 CNA ✓

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	R/L TYRE 4200 622 PUR	1	\$ 300.00	\$ 300.00
2	R/L TYRE RIM CNA	1	\$ 300.00	\$ 300.00
3	R/L WHEEL CAP 11	1	\$ 120.00	\$ 120.00
TOTAL				\$ 720.00

QUOTATION SUMMARY PAGE 02**CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING**

TO REMOVE REAR TAILGATE, REAR BUMPER, END PANEL AND BUMPER REINFORCEMENT OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS	\$ 800.00	780
TO RESPRAY REAR TAILGATE, END PANEL, REAR BUMPER, R/L DOOR AND F/L DOOR	\$ 800.00	✓
TO DISMANTLE & REPAIR cushion upholstery	\$ 200.00	50

To conduct wheel alignment TOTAL \$ 1,800.00 ✓

ESTIMATE REPORT

TOTAL PARTS COST	:	\$ 6,822.00
TOTAL LABOUR COST	:	\$ 1,800.00
TOTAL REPAIR COST	:	\$ 8,622.00

Kkk Auto Consultants hence notify

Repairer of the following:

Resurvey before/after spray painting

Display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-344030

102

309627

420

1680

519627

4157