

**AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.**

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)
 Tel : 6702 1555 Fax : 6702 1444
 Co. Reg No. : 201500047H GST No. : 201500047H
 Email : st.sim@autobacs.com.sg

not Affected
 in
 main
 25/9/24
 1/c & 4/50
 chphr. Hbby
 6 days

TO	: LIBERTY INSURANCE (SMX3873Y)	DATE	: 24-Sep-24
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXX465D	P -	
		S -	
		L -	
VEHICLE DETAILS		TOTAL :	
VEHICLE NO.	: SKD2213M	L/S -20% :	
MODEL / MAKE	: VOLKSWAGEN GOLF	SUB TOTAL :	
CHASSIS NO.	: WVVZZZ1KZCW108795		
ACCIDENT DETAIL			
DATE	: 20-Sep-24	CONTACT PERSON : MR. SIM 9844 0974	
TIME	: 12:00 HRS		

QUOTATION SUMMARY PAGE 01
CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER 1132.05 DUS	1	\$ 1,200.00	\$ 1,200.00
2	R/L TAILAMP INNER 290.45 CR	1	\$ 380.00	\$ 380.00
3	R/L TAILAMP OUTER CR	1	\$ 380.00	\$ 380.00
4	REAR TAILGATE R	1	\$ 2,500.00	\$ 2,500.00
5	R/L SIDE DOOR MIRROR BODY 11	1	\$ 700.00	\$ 700.00
6	REAR BUMPER LH REFLECTOR 56.75 CR	1	\$ 80.00	\$ 80.00
7	REAR END PANEL 071201	1	\$ 700.00	\$ 700.00
8	R/R FENDER INNER LINER 72.1	1	\$ 190.00	\$ 190.00
9	REAR BUMPER REINFORCEMENT 606.05 Bnt	1	\$ 650.00	\$ 650.00
TOTAL PRICE				\$ 6,780.00
LESS -10%				\$ (678.00)
SUB TOTAL PRICE				\$ 6,102.00

Rear bumper side holder HH 85.00 CR ✓

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	R/L TYRE 420 622 Pur	1	\$ 300.00	\$ 300.00
2	R/L TYRE RIM CR	1	\$ 300.00	\$ 300.00
3	R/L WHEEL CAP UN	1	\$ 120.00	\$ 120.00
TOTAL			\$	720.00

QUOTATION SUMMARY PAGE 02
CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO REMOVE REAR TAILGATE, REAR BUMPER, END PANEL AND BUMPER REINFORCEMENT OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS	\$ 800.00	780
TO RESPRAY REAR TAILGATE, END PANEL, REAR BUMPER, R/L DOOR AND F/L DOOR	\$ 800.00	✓
TO Dismantle & refix cushion upholstery	\$ 200.00	50

To conduct wheel alignment TOTAL \$ 1,800.00 ✓

ESTIMATE REPORT

TOTAL PARTS COST	:	\$ 6,822.00
TOTAL LABOUR COST	:	\$ 1,800.00
TOTAL REPAIR COST	:	\$ 8,622.00

As a Consultant hence notify
 Repairer of the following:
 Resurvey before/after spray painting
 Display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-344030

102

3096.17

420

1680

5196.27

4157