

ASS. REC. BY: Marcus

REF:

CS/ LIP 24090439/U nh3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKD 2213Mat Workshop m/s Arb hecs

of _____

Insured: SMX 38734

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$22K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKD 2213M Yr Regn: 10/11/11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA / new golf 1.4Make: VW / Sugar c.c. 1390Colour: white A/C: Insured / Std / NI / NASp.Reading: 173309 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZZ1KZCW 108795

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55-R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 20/09/24 D.O.I. 25/9/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Dep #11k.

100 unbrl 31-10-2026 MTA \$975.8
16/10/24 1/5 \$4150; in hand M.R. Sum (Red, \$4598.50, 52%)
alignant report at folder

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 6

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL



AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)
Tel : 6702 1555 Fax : 6702 1444
Co. Reg No. : 201500047H GST No. : 201500047H
Email : st.sim@autobacs.com.sg

not pulled in
main
25/9/24
1/c & 4/150
whph. Atkney
6 days

TO	: LIBERTY INSURANCE (SMX3873Y)	DATE	: 24-Sep-24
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXX465D	P -	
		S -	
		L -	
VEHICLE DETAILS			
VEHICLE NO.	: SKD2213M	TOTAL	:
MODEL / MAKE	: VOLKSWAGEN GOLF	L/S -20%	:
CHASSIS NO.	: WVVZZZ1K2CW108795	SUB TOTAL	:
ACCIDENT DETAIL			
DATE	: 20-Sep-24		
TIME	: 12:00 HRS	CONTACT PERSON : MR. SIM 9844 0974	

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER 1132.05 DCS	1	\$ 1,200.00	\$ 1,200.00
2	R/L TAILAMP INNER 290.45 CNE	1	\$ 380.00	\$ 380.00
3	R/L TAILAMP OUTER CNE	1	\$ 380.00	\$ 380.00
4	REAR TAILGATE R	1	\$ 2,500.00	\$ 2,500.00
5	R/L SIDE DOOR MIRROR BODY 11	1	\$ 700.00	\$ 700.00
6	REAR BUMPER LH REFLECTOR 56.75 CNE	1	\$ 80.00	\$ 80.00
7	REAR END PANEL 0019enf	1	\$ 700.00	\$ 700.00
8	R/R FENDER INNER LINER 70.1	1	\$ 190.00	\$ 190.00
9	REAR BUMPER REINFORCEMENT 606.05 Bnt	1	\$ 650.00	\$ 650.00
TOTAL PRICE				\$ 6,780.00
LESS -10%				\$ (678.00)
SUB TOTAL PRICE				\$ 6,102.00

Rear bumper s-be holder HH 85.00 CNE ✓

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	R/L TYRE 4200 602 Pur	1	\$ 300.00	\$ 300.00
2	R/L TYRE RIM CNE	1	\$ 300.00	\$ 300.00
3	R/L WHEEL CAP CNE	1	\$ 120.00	\$ 120.00
TOTAL			\$	720.00

QUOTATION SUMMARY PAGE 02

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO REMOVE REAR TAILGATE, REAR BUMPER, END PANEL AND BUMPER REINFORCEMENT OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS	\$ 800.00	780
TO RESPRAY REAR TAILGATE, END PANEL, REAR BUMPER, R/L DOOR AND F/L DOOR	\$ 800.00	✓
To Dismantle & refix cushion upholstery	\$ 200.00	50

To conduct wheel alignment 850 ✓ TOTAL 1,800.00

8748.50

ESTIMATE REPORT

TOTAL PARTS COST	:	\$ 6,822.00
TOTAL LABOUR COST	:	\$ 1,800.00
TOTAL REPAIR COST	:	\$ 8,622.00

Auto Consultants hence notify Reparer of the following:
Resurvey before/after spray painting
Display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

2-3440.30

102

3096.17

420

1680

5196.27

4157