

5b.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN	ICE LTD	Ref:	CS/INC24090440/Aqh3e2	
	75 BRAS BASAH ROAD		Date:	22/11/2024	
	INCOME CENTRE	SINGAPORE 189557	Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLU 7516E	Veh. Inspected	SNT 427G	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1296345-002	Excess	\$0.00	
	Assign From	MARCUS XIAO	Assign Date	25/09/2024	
2.	2. Vehicle Details				
	Make & Model	TOYOTA NOAH HYBRID	c.c	1797	
	Engine No.	2ZR3B01417	Year of Reg.	11/09/2024	
	Chassis No.	ZWR900188245	Colour	GREY	
	Odometer	2651 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	205/60 R16	TOYO	6	
	L/H Front Tyre	205/60 R16	TOYO	6	
	R/H Rear Tyre	205/60 R16	TOYO	6	
	L/H Rear Tyre	205/60 R16	TOYO	6	
4.	Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	5. General Information				
	Accident Date	22/09/2024	Inspection Date	25/09/2024 (13:44)	
	Survey held at KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978				
5a.	5a. Remarks				

Estimate Days of Repair

A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days

B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.