



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/LPC24090446/Evh3-1(N)

MS LONPAC INSURANCE BHD

Ref: ~~000/LPC24090446/Evh3~~

300 BEACH ROAD

Date: ~~25/09/2024~~ 16/10/2024

#17-04/07 THE CONCOURSE SINGAPORE 199555

Code: LPC2

1. Policy Particulars :- PRE-REPAIR SURVEY

Insured Veh.	GBE 2963H	Veh. Inspected	SKS 9748L
Policy No.	-	Coverage	0
Claim No.	23/24/24/VC05/029918	Excess	\$0.00
Assign From	CHARMAINE HUEY NI	Assign Date	25/09/2024 15/10/2024

2. Vehicle Details

Make & Model	C.C	-
Engine No.	Year of Reg.	-
Chassis No.	Colour	-
Odometer	Steering	- KM
Brakes	General	-
Modification(s)	NIL	

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre			
L/H Front Tyre			
R/H Rear Tyre			
L/H Rear Tyre			

4. Description of Damages

--

5. General Information

Accident Date	24/09/2024	Inspection Date	25/09/2024 (15:24)
Survey held at	25 KAKI BUKIT ROAD 4 #05-38 SYNERGY@KAKI BUKIT SINGAPORE 417800		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days