

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT24/SLE1332S/TPC

MINDEF

Ministry Of Defence (MINDEF)

303 Gombak Dr

Singapore 669645

QUOTATION

Dear Sir,

Cost of Repair to Vehicle SLE1332S

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Rear bumper	1	2,236.20	2,236.20
2.	Rear bumper bracket RH	1	104.50	104.50
3.	Rear bumper clips	10	3.50	35.00
4.	Boot	1	2,427.00	2,427.00
5.	Rear RH taillamp	1	677.90	677.90
6.	Rear RH fender	1	1,972.50	1,972.50
7.	Rear RH passenger door	1	2,393.90	2,393.90
8.	Sealant	3	40.00	120.00
9.	Reverse sensor	1	350.00	350.00
10.	70 KM/H sticker	1	15.00	15.00
11.	Emblem RH	1	75.00	75.00
12.	Toyota emblem	1	65.00	65.00
13.	Harrier emblem	1	95.00	95.00
14.	Transfer boot fittings	1	150.00	150.00
15.	Remove & refit rear windscreen to assist repair	1	120.00	120.00
16.	Remove & refit RH rear quarter glass to assist repair	1	60.00	60.00

th-
cur-
na-
cur-
cur-
but-
bt-
na-60
x
x
x
na-
na-
x 7 40
x
✓

17.	Remove & refit RH rear passenger glass to assist repair	1	90.00	90.00	Go
18.	Transfer Rear RH door fittings	1	100.00	100.00	Go
19.	Ceramic coating	1	800.00	800.00	? possible invoice
20.	Check wiring	1	20.00	20.00	✓
21.	Spray painting	1	1,000.00	1,000.00	800
22.	Labour charges	1	1,200.00	1,200.00	800
SUB-TOTAL				S\$14,107.00	

- Price before gst

Thank you.

Taufik 97495749
 'wp' 30/9/24 330pm
 Taufik c/WhatsApp
 6-7 days
 L/S Resurvey after repair.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: