

ASS. REC. BY: Tauph REF: CS/FC/24060181/Typ3


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: 114 50K
 (Client's Record)
 Make of Veh: _____

Veh No: SG 6136R Yr Regn: 2019 04
 Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: MAN A95 c.c. 10000
 Colour: Green A/C: Insured / Std / NI / NA
 Sp. Reading: 485762 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WMAA 95777K F009077
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: NW / S/Rim / STD A/Rim or _____
 Tyre Size: F: 275/70R22.5
 R: ^ ^ (D)

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
\$340K
 Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 20 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REP. / 24 HRS
 Date: _____ Person Contacted: Sam Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Fivenza
 Front Rear
 R/Bal. 8 mm R/Bal. 8/8 mm
 L/Bal. 8 mm L/Bal. 8/8 mm
 D.O.A. _____ D.O.I. 24/6/24
 Survey held at Manderi Depot
 Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or
Frt N/S, Rear O/S
 The U/G / Chassis frame / Body Structure affected due to collision.



Date / Time	Action / Instruction
18/07/24	Rachel informed owner withdraw claims
18/07/24	Submit Preli. report.

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) 18/07 Typist
 Date/Time, File Return to? _____
 2) _____
 Rep. Format: _____
 Lump Sum / L.B.K. (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Inv (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____ \$ + RS. \$ _____
 Photos _____
 Others _____
 TOTAL _____

ESTIMATED ACCIDENT REPAIR COST



TOWER TRANSIT

Co. / GST Reg No. 201419417K

ACCIDENT TIME REPORTED	06:38 HRS	BUS REGISTRATION NUMBER	SG6136R
ACCIDENT DATE	8-Jun-24	BUS TYPE (SD/DD)	DD
BUS CAPTAIN NAME	WONG KIM THYE	BUS ROUTE NO.	
CLAIM AGAINST	MSFC	BUS ADVERT (Y/N)	Y

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	UPPER FRONT WIDNSCREEN FW1 <i>cra</i>	1	\$ 5,250.00
2	OS WINDOW GLASS R13 <i>ent</i>	1	\$ 750.00
3	OS WINDOW GLASS R14 <i>ent</i>	1	\$ 750.00
4	OS WINDOW GLASS R15 <i>ent</i>	1	\$ 750.00
5	REAR DOME FRP <i>cra</i>	1	\$ 4,200.00
6	UPPER SERVICE AIRCON <i>bt</i>	1	\$ 3,900.00
7	LOWER AIRCON SVC DOOR <i>bt</i>	1	\$ 3,900.00
8	AIRCON SVC DOOR LOCK <i>dis</i>	2	\$ 120.00
9	CROSSBAR COVER <i>bt</i>	1	\$ 360.00
10	REAR ENGINE DOOR <i>bt</i>	1	\$ 5,250.00
11	ENGINE DOOR CATCH <i>bt</i>	1	\$ 154.00
12	OS REAR ENGINE REFLECTOR(RED) <i>cra</i>	1	\$ 203.00
13	NS REAR ENGINE REFLECTOR(RED) <i>rel</i>	1	\$ 203.00
14	NS DOOR HINGE <i>bt</i>	1	\$ 192.50
15	OS DOOR HINGE <i>bt</i>	1	\$ 192.50
16	OS GAS SPRING 500N 27" W/O LOCK <i>bt</i>	2	\$ 245.00
17	OS ENGINE DOOR GAS SPRING BRACKED <i>bt</i>	1	\$ 203.00
18	REAR BUMPER <i>cra</i>	1	\$ 2,625.00
19	REAR FRAME BOTTOM SUPPORT <i>bt</i>	1	\$ 980.00
20	RADIATOR UNDERNEATH COVER <i>bt</i>	1	\$ 1,680.00
21	OS REAR BUMPER <i>cra</i>	1	\$ 1,470.00
22	REAR ENGINE REFLECTOR ROUND(RED) <i>cra</i>	1	\$ 52.50
23	REAR LAMP STOP ASSY LED(RED) <i>mis</i>	1	\$ 665.00
24	REAR SIGNAL LAMP ASSY LED(CLEAR) <i>mis</i>	1	\$ 665.00
25	REAR GOG LAMP BULB(RED) <i>mis</i>	1	\$ 192.50
26	REAR REVERSE LAMP BULB(CLEAR) <i>mis</i>	1	\$ 192.50
27	RADIATOR BOTTOM PANEL R16 <i>bt</i>	1	\$ 203.00
28	OS REAR RADIATOR DOOR <i>bt</i>	1	\$ 2,380.00

ESTIMATED ACCIDENT REPAIR COST



Co. / GST Reg No. 201419417K

29	OS REAR RADIATOR NETTING <i>bt</i> ✓	1	\$ 1,350.00
30	RADOATOR DOOR FRAME R19 <i>bt</i> ✓	1	\$ 1,120.00
31	RADIATOR DOOR HINGE <i>bt</i> ✓	2	\$ 245.00
32	DOOR LOCK <i>bt</i> ✓	4	\$ 126.00
33	OS REAR AIR TANK DOOR R15 <i>mis</i> ✓	1	\$ 980.00
34	OS REAR AIR TANK DOOR FRAME R15 <i>bt</i> ✓	1	\$ 1,050.00
35	LHS HINGE SIDE FLAP (DHGE-0058-00) <i>mis</i> ✓	1	\$ 227.50
36	RHS HINGE SIDE FLAP (DHGE-0057-00) <i>mis</i> ✓	1	\$ 227.50
37	DOOR STOPPER W/SCREW <i>mis</i> ✓	2	\$ 3,150.00
38	GAS SPRING 200N-084670 <i>mis</i> ✓	2	\$ 196.00
39	OS TAG WHEELARCH PANEL R11 <i>bt</i> ✓	1	\$ 840.00
40	WHEELARCH TRIM FRP <i>cva</i> ✓	1	\$ 350.00
41	OS REAR SIDE ALUMINIUM PILLAR 2765MM <i>bt</i> ✓	1	\$ 1,330.00
42	OS REAR SIDE ALUMINIUM PILLAR 2577MM 100MM <i>bt</i> ✓	2	\$ 3,850.00
43	PILLAR REPAIR KIT 5 <i>rel</i> ✓	1	\$ 280.00
44	L CORNER R120 ANGEL <i>rel</i> ✓	4	\$ 350.00
45	SEEALANT BLACK BOSTIK 600ML 7008 <i>rel</i> ✓	12	\$ 756.00
46	EURO 6 EMBLEM PLATE <i>rel</i> ✓	1	\$ 70.00
47	TTS LOGO STICKER <i>rel</i> ✓	1	\$ 70.00
48	60KH/H STICKER <i>rel</i> ✓	1	\$ 35.00
49	OS REAR CCTV CAMERA <i>dis</i> ✓	2	\$ 3,360.00
50	RADIATOR A95 <i>? photo</i>	1	\$ 10,230.00
51	OIL COOLER A95 <i>? photo</i>	1	\$ 7,800.00
52	WATER PUMP BELT/FAN BELT <i>fu</i> ✓	1	\$ 84.00
53	AIRCON BELT A95 <i>fu</i> ✓	1	\$ 84.00
54	TAILPIPE ASSEMBLY WITH NOX SENSOR <i>?</i>	1	\$ 5,600.00
		9% GST	\$ 7,334.06
		PARTS TOTAL COST	\$ 81,489.50

ESTIMATED ACCIDENT REPAIR COST



Co. / GST Reg No. 201419417K

SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE :- <ul style="list-style-type: none"> DISMANTLE AND REPLACE ITEM NO: 1-54 	\$ 35,100.00
TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS :- <ul style="list-style-type: none"> OS REAR PILLAR STRUCTURE BRACKETS OS TAG WHEEL MUDGUARD 	\$ 1,300.00
SPRAY PAINTING :- <ul style="list-style-type: none"> REAR DOME UPPER SVC DOOR LOWER AIRCON SVC DOOR CROSS BAR COVER REAR ENGINE DOOR REAR BUMPER OS REAR BUMPER RADIATOR DOOR & BOTTOM PANEL OS REAR AIR TANK DOOR OS TAG WHEELARCH PANEL&WHEELARCH TRIM FRP 	\$ 6,400.00
SPRAY PAINTING \$640 PER PANEL	9% GST
LABOUR CHARGES \$650 PER DAY	\$ 3,852.00
	LABOUR TOTAL COST \$ 46,652.00

SECTION 3 : RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 4 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

	DATE IN	8/Jun/2024
	DATE & TIME SURVEY	
	DATE OUT	
BUS TYPE (SD / DD)	DD	TOTAL NUMBER OF DAYS
		20
LOSS OF USE COST		\$8,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495749
Not Authorise 24/6/24
To Revent Ex: to be advise
PIP Resurvey new part, before paint
taufik@lkkauto.com
20 days

SUMMARY	
SECTION NO.	COST
1	\$ 81,489.50
2	\$ 46,652.00
3	-
4	\$ 8,000.00
TOTAL	\$ 136,141.50