

# HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778  
E-mail: hdperfectautowork@gmail.com



HD PERFECT  
AUTOWORK PTE LTD

DATE : 18.09.2024

TO : **AIG** MOTOR CLAIMS DEPTS  
VEHICLE NO : **GBK2257G**  
MODEL : **TOYOTA DYNA**  
DATE OF ACCIDENT : 17.09.2024  
TIME OF ACCIDENT : 15:30 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Old</i>	1	\$ 727.10	\$ 727.10
2	FRONT BUMPER BRACKET <i>Best</i>	2	\$ 253.30	\$ 506.60
3	FRONT BUMPER FOGLAMP <i>new</i>	2	\$ 439.40	\$ 878.80
4	FRONT BUMPER FOGLAMP COVER <i>new</i>	2	\$ 165.60	\$ 331.20
5	FRONT GRILLE <i>new</i>	1	\$ 795.20	\$ 795.20
6	FRONT GRILLE LOGO <i>new</i>	1	\$ 88.10	\$ 88.10
7	FRONT PANEL <i>Dented</i>	1	\$ 1,156.70	\$ 1,156.70
8	FRONT PANEL EMBLEM 'DYNA' <i>new</i>	1	\$ 96.20	\$ 96.20
9	FRONT WINDSCREEN RUBBER <i>new</i>	1	\$ 363.50	\$ 363.50
10	FRONT WINDSCREEN GLASS <i>changed to original</i>	1	\$ 1,532.70	\$ 1,532.70
11	FRONT WIPER PANEL (OUTER) <i>Dented</i>	1	\$ 476.20	\$ 476.20
12	FRONT WIPER PANEL (INNER) <i>new</i>	1	\$ 798.30	\$ 798.30
13	FRONT WIPER BLADE	2	\$ 72.60	\$ 145.20
14	FRONT WIPER ARM	2	\$ 179.80	\$ 359.60
15	FRONT WIPER LINKAGE	1	\$ 293.40	\$ 293.40
16	FRONT WIPER LINKAGE MOTOR <i>new</i>	1	\$ 678.80	\$ 678.80
17	FRONT NOZZLE <i>new</i>	2	\$ 47.40	\$ 94.80
18	HEAD LAMP <i>new</i>	2	\$ 981.30	\$ 1,962.60
19	HEAD LAMP LOWER RUBBER <i>new</i>	2	\$ 47.20	\$ 94.40
20	FRONT CORNER PANEL <i>new</i>	2	\$ 329.80	\$ 659.60
21	FRONT CORNER TOP JOINT GARNISH <i>new</i>	2	\$ 26.40	\$ 52.80
22	FRONT CORNER SUPPORT PANEL BRACKET <i>new</i>	2	\$ 75.30	\$ 150.60

New/old

1340

TO : **AIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **GBK2257G**  
 MODEL : **TOYOTA DYNA**  
 DATE OF ACCIDENT : 17.09.2024  
 TIME OF ACCIDENT : 15:30 HOURS

23	SIDE MIRROR LH <i>Best part</i>	1	\$ 588.50	\$ 588.50	+ ✓
24	SIDE MIRROR STAND LH (AUTO) <i>new part</i>	1	\$ 678.40	\$ 678.40	+ ✓
25	SIDE MIRROR TOP COVER LH <i>new</i>	1	\$ 32.60	\$ 32.60	+ ✓
26	SIDE MIRROR ROUND LH <i>new</i>	1	\$ 185.40	\$ 185.40	+ ✓
27	FRONT CABIN HINGE <i>new</i>	1	\$ 3,270.00	\$ 3,270.00	+ ✓
28	FRONT BRAKE PIPE <i>new</i>	4	\$ 323.00	\$ 1,292.00	+ ✓
29	AIR CON BLOWER MOTOR <i>new</i>	1	\$ 1,394.00	\$ 1,394.00	+ ✓
30	AIR CON COOLING COIL <i>new</i>	1	\$ 2,439.00	\$ 2,439.00	+ ✓
31	AIR CON PIPE <i>new</i>	2	\$ 475.00	\$ 950.00	+ ✓
32	AIR CON HOSE <i>new</i>	2	\$ 388.00	\$ 776.00	+ ✓
33	FRONT DASHBOARD <i>new</i>	1	\$ 1,250.40	\$ 1,250.40	+ ✓
34	FRONT DASHBOARD CENTER LOWER COVER GARNISH	1	\$ 396.40	\$ 396.40	+ ✓
35	FRONT DASHBOARD SWITCH CONTROL PANEL	1	\$ 764.30	\$ 764.30	+ ✓
36	FRONT DASHBOARD SIDE LOWER COVER GARNISH LH	1	\$ 568.20	\$ 568.20	+ ✓
37	FRONT WIRE HARNESS	1	\$ 7,200.70	\$ 7,200.70	+ ✓
38	WASHER TANK	1	\$ 168.30	\$ 168.30	+ ✓
39	AIR CON CONDENSER	1	\$ 987.70	\$ 987.70	+ ✓
40	AIR CON CONDENSER SUPPORT BRACKET	1	\$ 236.30	\$ 236.30	+ ✓
41	AIR CON CONDENSER FAN MOTOR C/W COWLING	1	\$ 429.80	\$ 429.80	+ ✓
42	AIR CON BLOWER	1	\$ 1,758.60	\$ 1,758.60	+ ✓
43	AIR CON COOLING COIL	1	\$ 2,379.20	\$ 2,379.20	+ ✓
44	AIR CON HEATER	1	\$ 983.80	\$ 983.80	+ ✓
45	AIR CON PIPE	2	\$ 396.50	\$ 793.00	+ ✓
46	FRONT DOOR STEP PANEL	2	\$ 302.50	\$ 605.00	+ ✓
47	TAILGATE <i>Dented</i>	1	\$ 1,370.00	\$ 1,370.00	+ ✓
48	TAILGATE HINGE <i>2 pieces Bent</i>	4	\$ 165.00	\$ 660.00	+ ✓
49	TAILGATE SIDE LOCK <i>new</i>	2	\$ 125.00	\$ 250.00	+ ✓
50	TAILGATE STOPPER RUBBER <i>HH missing</i>	2	\$ 35.00	\$ 70.00	+ ✓
51	TAILGATE STOPPER BRACKET <i>195</i>	2	\$ 175.00	\$ 350.00	+ ✓
52	TAILGATE STICKER 'TOYOTA' <i>new</i>	1	\$ 167.60	\$ 167.60	+ ✓
53	SIDE GATE <i>195</i>	2	\$ 1,968.90	\$ 3,937.80	+ ✓
54	SIDE GATE SAFETY LOCK <i>new</i>	2	\$ 132.10	\$ 264.20	+ ✓
55	TAIL LAMP <i>LH cut</i>	2	\$ 245.00	\$ 490.00	+ ✓

330  
 35  
 245

TO : **AIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **GBK2257G**  
 MODEL : **TOYOTA DYNA**  
 DATE OF ACCIDENT : 17.09.2024  
 TIME OF ACCIDENT : 15:30 HOURS

56	TAIL LAMP SUPPORT BRACKET	2	\$ 185.00	\$ 370.00
57	REAR STICKER 'DYNA'	1	\$ 45.00	\$ 45.00
58	REAR END PANEL	1	\$ 1,245.00	\$ 1,245.00
59	REAR CHASSIS MEMBER RH	1	\$ 1,068.50	\$ 1,068.50

+  
 ✓  
 485  
 +

11402.10  
 8551.570

TOTAL PRICE \$ 52,658.10  
 LESS 25% \$ 13,164.53  
**SUB TOTAL PRICE \$ 39,493.58**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE	1	\$ 50.00	\$ 50.00
2	FRONT GRILLE CLIP (SET)	1	\$ 40.00	\$ 40.00
3	FRONT PANEL SEALANT	1	\$ 150.00	\$ 150.00
4	DASHBOARD CLIP (SET)	1	\$ 150.00	\$ 150.00
5	DASHBOARD CENTER GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
6	FRONT WINDSCREEN GLASS SEALANT	1	\$ 80.00	\$ 80.00
7	FRONT WINDSCREEN GLASS INNER SEAL	1	\$ 60.00	\$ 60.00
8	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00
9	TAIL GATE ALUMINIUM COVER (SPECIAL TYPE)	1	\$ 680.00	\$ 680.00
10	TAIL GATE '70KM/H' STICKER	1	\$ 40.00	\$ 40.00
11	SIDE GATE ALUMINIUM (SPECIAL TYPE)	2	\$ 850.00	\$ 1,700.00
12	SIDE GATE COMPANY STICKER (SPECIAL TYPE)	2	\$ 380.00	\$ 760.00
13	REAR END PANEL SEALANT	1	\$ 150.00	\$ 150.00
14	REAR STEP BRACKET	1	\$ 80.00	\$ 80.00
15	REAR FLOOR TOP ALUMINIUM PANEL (SPECIAL TYPE)	1	\$ 3,800.00	\$ 3,800.00
16	REVERSE SENSOR (SET)	1	\$ 220.00	\$ 220.00

30  
 30  
 60  
 +  
 +  
 40  
 30  
 30  
 350  
 15  
 4  
 ✓  
 +  
 50  
 +  
 20

1595

TOTAL \$ 8,060.00

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 2,000.00	800
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,200.00	800
3	TO SPRAY TUFF COAT	\$ 250.00	40

TO : **AIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **GBK2257G**  
 MODEL : **TOYOTA DYNA**  
 DATE OF ACCIDENT : 17.09.2024  
 TIME OF ACCIDENT : 15:30 HOURS

4	WIRING, BULB CHECKING	\$ 80.00	<del>80</del> 30
5	CONDUCT WATER TER LEAKAGE TEST	\$ 80.00	X
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	X
7	REFOCUS HEADLAMP BEAM	\$ 60.00	X
8	REMOVE AND REFIX AIRCON BLOWER, COOLING COIL, AIR CON CONDENSER AND REFILL AIRCON GAS	\$ 150.00	X
9	REMOVE AND REINSTALL DASHBOARD	\$ 650.00	X
10	REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	✓
11	REMOVE AND REFIX FRONT VIDEO RECORDER	\$ 80.00	<del>80</del> 50
12	RESET RADIO SYSTEM	\$ 200.00	X
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	\$ 180.00	X

1860

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ <del>1,400.00</del>	600
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ <del>1,400.00</del>	600
3	REMOVE AND REFIX REAR RAILING	\$ 350.00	X
4	REMOVE AND REFIX REVERSE SENSOR	\$ <del>80.00</del>	50
5	REMOVE AND REFIX REAR FLOOR ALUMINIUM	\$ 650.00	X

TO : **AIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **GBK2257G**  
 MODEL : **TOYOTA DYNA**  
 DATE OF ACCIDENT : 17.09.2024  
 TIME OF ACCIDENT : 15.30 HOURS

6	REAR CHASSIS ALIGHMENT	\$	250.00	X
<b>TOTAL</b>		<b>\$</b>	<b>9,530.00</b>	

1250

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 47,553.58  
 TOTAL LABOUR COST : \$ 9,530.00  
 TOTAL REPAIR COST : \$ 57,083.58

*Aban*  
*h/s 19/09/24*  
*10 Days*

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN  
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
 IRENE  
 HP : 8297 9787

total: 1325657  
 h/s: 10.6K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray priming
- To clearly delineate/outline damaged areas
- Parts prices are subject to our approval
- Third party survey is not a "No. cost" procedure
- No illegal modifications allowed
- Supplies are subject to our approval and subject to our pricing from our suppliers

CLA  
 Acknowledged by Repairer: \_\_\_\_\_  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

DECLARATION  
 I hereby declare that the information provided herein is true and correct to the best of my knowledge and belief.

NAME OF VICTIM: \_\_\_\_\_  
 DATE OF ACCIDENT: \_\_\_\_\_  
 MODEL: \_\_\_\_\_  
 VEHICLE NO: \_\_\_\_\_  
 HP: \_\_\_\_\_

Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_