

ASS. REC. BY:

REF:

1051

CS/10524090450/Knp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

\$ 35K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

10/28

Person Contacted:

Vehicle: IN / OUT

Veh No:

STK 7503T

Yr Regn:

10, 98

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M. E200 Honda

1796

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

208094

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDB 2110412B 370955

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

22/9/24

D.O.I.

1/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/10 11:00 @ 38000 Cash (Red. \$ 5032.80, 56%)

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

3

Resurvey No. of Trlp:

Survey Fee:

Transportation

S + RS. \$

Fees

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	664G
Vehicle Details	
Vehicle No.:	SJK7503T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	23 Sep 2024
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200 NGT
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	27195631106460
Chassis No.:	WDB2110412B370955
Maximum Power Output:	120.0 kW (160 bhp)
Open Market Value:	\$53,998.00
Original Registration Date:	31 Oct 2008
First Registration Date:	31 Oct 2008
Transfer Count:	2
Actual ARF Paid:	\$32,399.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2028
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$32,279.00
COE Rebate Amount:	\$13,241.00
Total Rebate Amount:	\$13,241.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 23 Sep 2024

OK

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 07166

Vehicle Insured : SMM6056C
Accident Date : 22-Sep-2024

Date : 23-Sep-2024

Our Ref : 024184 (ECICS) / CHAN

PAGE : 1

PETER CHEW KIM HUAT
51 HUME AVE
#04-01
Singapore 598750

*Not Notified
1/1 Rng & 3800h
Resurvey After Paint*

ESTIMATED COST OF REPAIR FOR M/BENZ E200 NGT SJK7503T

3 days

1 pc Rear bumper fascia
1 pc Rear bumper centre chrome
2 pcs Rear bumper side chrome
1 pc Rear bumper reinforcement
1 pc Boot lid
1 pc Boot lid "E200" emblem
1 pc Boot lid "COMPRESSOR" emblem
1 pc Boot lid star logo

*Pr? @ S\$140.00
1500*

Bu 1,150.00 ✓
nd 182.00 ✓
na 280.00 ✓
Bu 3,100.00 ✓
R 1,700.00 x
na 53.00 ✓
na 55.00 ✓
na 28.00 ✓

6,548.00

Add: 10% : 654.80

1 pc Rear bumper reverse sensor(4pc
1 pc Rear bumper rivet (set)

7,202.80
scr 400.00 sn ✓
na 30.00 sn ✓

To putty and spray replaced parts

4401 600.00 ~~2501~~

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

600.00 *3001*

Total : S\$ 8,832.80

Singapore Dollars Eight Thousand Eight Hundred
and Thirty Two and Cents Eighty Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: