

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 07166

Vehicle Insured : SMM6056C
Accident Date : 22-Sep-2024

Date : 23-Sep-2024

Our Ref : 024184 (ECICS) / CHAN

PAGE : 1

PETER CHEW KIM HUAT
51 HUME AVE
#04-01
Singapore 598750

*Not Notified
1/Rep & 3800h
Resurvey After Paint*

ESTIMATED COST OF REPAIR FOR M/BENZ E200 NGT SJK7503T

3 days

1 pc Rear bumper fascia
1 pc Rear bumper centre chrome
2 pcs Rear bumper side chrome
1 pc Rear bumper reinforcement
1 pc Boot lid
1 pc Boot lid "E200" emblem
1 pc Boot lid "COMPRESSOR" emblem
1 pc Boot lid star logo

*Pr? @ S\$140.00
1500*

Bu 1,150.00 ✓
nd 182.00 ✓
na 280.00 ✓
Bu 3,100.00 ✓
R 1,700.00 x
na 53.00 ✓
na 55.00 ✓
na 28.00 ✓

6,548.00

Add: 10% : 654.80

1 pc Rear bumper reverse sensor(4pc
1 pc Rear bumper rivet (set)

7,202.80
scn 400.00 sn ✓
na 30.00 sn ✓

To putty and spray replaced parts

4401 600.00 ~~2501~~

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

600.00 *3001*

Total : S\$ 8,832.80

Singapore Dollars Eight Thousand Eight Hundred
and Thirty Two and Cents Eighty Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: