


Strides Vehicle Repair Estimate

Group :	Buses / Taxis / <u>Private Car</u>	Ref. No. :	
Reg. No. :	PC8703Y	Reg. Date :	23/10/2019
Make / Model :	TOYOTA HIACE	Mileage :	
Chassis No. :	JTFST22PX00038773	Rental/Replacement Vehicle :	Yes / No
Name of Driver :	JUMANI BIN SENGARI		
Date/Time of Accident :	13-05-2024 @ 14:15		
Surveyor is Required ?	YES / NO		
If Yes, VICOM / LKK / AIS / Others	MSIG :		
Vehicle is Towed Back ?	YES / NO	Date / Ti :	
Accident reporting date :			
Type of Accident : Skid / Head-Rear / Head-On / Side Swipe / Others			
Special Instruction to ARC, if any :			
Signed :		Date :	

The damages on the vehicle are as indicated in the following diagram :



Accident Repair Job Card No. :		Date Prepared :	
Summary of Repair Estimates		Repair Completed :	
	Quotation from ARC		Adjusted by Surveyor, if applicable
Total Labour Charges :	\$ 2,180.00		\$ -
Total Spray Painting Charges :	\$ 1,300.00		\$ -
Total Material Charges :	\$ -		\$ -
Other Charges :	\$ 30.00		\$ -
TOTAL :	\$ 3,510.00		\$ -
	Lump Sum Repair, if any :		
No. of Repair Days :	[9] days		[7] days
Signature :	Prepared by:	Adjusted by:	Taufik 97495749 / 1/5 Resuming after repair

QN No. :		Invoice No. :	
Signed :		Date :	

Taufik @ lkkanta.com
Invoice Date

Part 1 - Labour Works

Page (2)

Job Scope	Quotation from ARC	
TO REMOVE AND RENEW SIDE DAMAGED PARTS; REPLACE REALIGNED ALL AFFECTED PARTS	\$ 1,800.00	900
TO REMOVE/ REFIX WIRING CHECKS	\$ 120.00	30
TO VACUUM INTERIOR AND CLEAN EXTERIOR	\$ 60.00	X

TO APPLY RUST-PROOFING ON AFFECTED AREA	\$	100.00	40
TO REPLACE SUNDRY PARTS	\$	100.00	X
Total Labour Cost	\$	2,180.00	\$

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	
TO RESPRAY ALL AFFECTED AREAS	\$	1,300.00
TAILGATE, PANEL QUARTER LH, END PANEL, REAR BUMPER		1000
Spray Painting	\$	1,300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Page (3)

Job Scope	Quotation from ARC	
BUMPER CLIPS	\$	30.00
		nel ✓
Total Other Costs	\$	30.00

Part 4 - Spare Parts / Material Usage

Ref No.:

To be completed by Service Advisor, ARC							
Part Number	Parts Description	Qty	Cost Price (\$)	COST PLUS 10%	Final Price (\$)	Repair (R) / Replace (/)	Not given (X) / pair (R) / Replace (/)
	COVER, REAR BUMPER	1	TBC	10%	#VALUE!	REPLACE	Cher ✓
	COVER, REAR BUMPER, UPR LH	1	TBC	10%	#VALUE!	REPLACE	de ✓
	SUPPORT, REAR BUMPER SIDE, LH	1	TBC	10%	#VALUE!	REPLACE	de ✓
	SUPPORT REAR BUMPER SIDE NO 2 LH	1	TBC	10%	#VALUE!	REPLACE	?
	REVERSE SENSOR	1	TBC	10%	#VALUE!	REPLACE	X
	MEMBER SUB-ASSY REAR FLOOR CROSS OUTER	1	TBC	10%	#VALUE!	REPLACE	Rp
	DUCT ASSY, QUARTER VENT, LH	1	TBC	10%	#VALUE!	REPLACE	?
	PANEL, QUARTER, LH	1	TBC	10%	#VALUE!	REPLACE	buc ✓
	PLATE, CAB REAR PILLAR, LOWER LH	1	TBC	10%	#VALUE!	REPLACE	X
	FRAME SUB-ASSY, BACK DOOR OPENING SIDE, LH	1	TBC	10%	#VALUE!	REPLACE	X
	REINFORCEMENT, BACK DOOR OPENING, LOWER LH	1	TBC	10%	#VALUE!	REPLACE	X
	ADVERTISEMENT STICKER (PANEL QUARTER LH)	1	TBC	10%	#VALUE!	REPLACE	nel ✓
	PANEL SUB-ASSY, BACK DOOR	1	TBC	10%	#VALUE!	REPLACE	Rp
	LENS, REAR COMBINATION LAMP, LH	1	TBC	10%	#VALUE!	REPLACE	cur ✓
	ADVERTISEMENT STICKER (TAILGATE)	1	TBC	10%	#VALUE!	REPLACE	nel ✓
	STICKER 70KM	1	\$ 15.00	0%	\$ 15.00	REPLACE	nel ✓
TOTAL MATERIALS			\$ 15.00	10%	#VALUE!		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) and resurvey
- Parts prices are submitted on a "no prejudice" basis
- Third party survey is a "no prejudice" basis
- No illegal modification(s) is/are
- Supplementary item(s) must be approved and is submitted for approval from Insurance Company

As Repairer

S

D