

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SLG2054C

Not Authored
L1 Rmp @ 8150/h

Recovery After Pain
5 days

No.	Qty	Nett Items
1	1	Rear bumper
2	2	Rear bumper side reflector
3	1	Rear bumper RH tow cover
4	2	Rear bumper side retainer
5	1 set	Rear bumper clips
6	1	Rear bumper inner foam 16810
7	1	Rear bumper inner reinforcement
8	2	Taillamp
9	1	Rear tailgate 3630.60
10	1	Rear tailgate LH "QASHQAI" emblem
11	1	Rear tailgate top lock
12	1	Rear tailgate weatherstrip
13	1	Rear tailgate inner trim board clips
14	1	Rear end panel 598.70
15	1	Rear end panel top garnish

\$ Bu	880.10	✓
\$ Bu	145.00	x
\$ m17	28.10	✓
\$ Dis	110.20	✓
\$ m	50.00	✓
\$ CM	282.20	✓
\$ B1	676.70	✓
NLS CBA	1,042.60	✓
\$ B1	3,630.60	✓
\$ m	116.90	✓
\$ R	252.10	x
119.60SN	\$ Rd/dis	239.20 304SN
\$ Na	60.00	x
\$ B1	598.70	✓
\$ m17	95.90	✓
\$	8,208.30	
Less 10%	\$	820.83
Total :	\$	7,387.47

	Special Nett Items
16	1 set Reverse sensors (C/w 4 pcs)
17	1 set Rear windscreen sealant
18	1 set Rear end panel sealant

\$ palom	550.00	✓ 480SN
\$ m	60.00	40SN
\$ m	60.00	30SN
Total :	\$	670.00

	Labour
1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.
2	To putty and spray Spray Paintings charges.
3	To check wirings & lightings.
4	To remove, refix reverse sensors.
5	To remove, refix rear windscreen glass.
6	To remove, refix rear tailgate fittings.
7	To remove, refix rear upholstery & attachments.
8	To supply and apply anti rust treatment.

\$	900.00	700L
\$	1,000.00	600L
\$	40.00	20L
\$	80.00	60L
\$	140.00	120L
\$	80.00	60L
\$	120.00	60L
\$	70.00	60L
Total :	\$	2,430.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Parts and Labour : \$ 10,487.47