



CYCLE &amp; CARRIAGE

## CYCLE &amp; CARRIAGE AUTOMOTIVE PTE LIMITED

## Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

MITSUBISHI  
MOTORS

Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X


| Invoice Name & Address  | Owner Name & Vehicle Info |                                 |
|---|---------------------------|---------------------------------|
| Mr Chua Tian Seong<br><br>146 Rivervale Drive<br>#06-505<br>Singapore 540146<br><br>Contact No Mobile: 96641766 | Cust No/Name              | /Mr Chua Tian Seong             |
|   | Reg No/Reg Date           | SNF5377H / 01/06/2022           |
|   | Date In/Mileage           | 24/09/2024/ 57309               |
|   | Chassis No                | JMAXTGK1WNZ000146               |
|   | Engine No                 | 4B40JL4952                      |
|   | Make/Model                | MIT/ECLIPSE CROSS CLASSIC (T04) |
|   | Colour/Trim               | W85 WHITE DIAMOND / BK BLACK    |

| Account No  | Terms | Date/Time Printed | CSE | Operator                  | WIP No     |       |         |
|---|-------|-------------------|-----|---------------------------|------------|-------|---------|
| CTP00040  | Cash  | 07/10/2024/ 17:09 | REN | 979 / Renemer Ramirez Bag | 26917      |       |         |
| Description of Goods / Services   |       |                   |     | Qty                       | Unit Price | Disc% | Amount  |
| Z TEXT  |       |                   |     |                           |            |       |         |
| ACCIDENT ON 24/09/2024 ALONG MANDAI ROAD                                  |       |                   |     |                           |            |       |         |
| OWNER CLAIMING THIRD PARTY CLAIM  |       |                   |     |                           |            |       |         |
| REQUIRED REPLACEMENT VEHICLE  |       |                   |     |                           |            |       |         |
| TP#: GBM5175D TP INS: INDIA INT'L INSURANCE                               |       |                   |     |                           |            |       |         |
| A 10028901  |       |                   |     |                           |            |       | 280.00  |
| TO CARRY OUT DIAGNOSTIC CHECK ON MUT AND CLEAR TROUBLE CODE               |       |                   |     |                           |            |       |         |
| A 90000001  |       |                   |     |                           |            |       | 80.00   |
| TO CHECK WIRING AND ELECTRICAL SYSTEM                                     |       |                   |     |                           |            |       |         |
| E PNT88000  |       |                   |     |                           |            |       | 320.00  |
| TO REPLACE DAMS, SPACERS & FASTENERS                                      |       |                   |     |                           |            |       |         |
| TO REMOVE & RE-INSTALL TAILGATE GLASS                                     |       |                   |     |                           |            |       |         |
| E PNT88000  |       |                   |     |                           |            |       | 320.00  |
| TO TRANSFER TAILGATE COMPONENTS & MECHANISM                               |       |                   |     |                           |            |       |         |
| E PNT88000  |       |                   |     |                           |            |       | 320.00  |
| TO REMOVE & RE-INSTALL TRIMS, CARPETS, FLOOR BOARDS TO FACILITATE         |       |                   |     |                           |            |       |         |
| REPAIR ON REAR ACCIDENT AFFECTED AREAS                                    |       |                   |     |                           |            |       |         |
| E PNT88000  |       |                   |     |                           |            |       | 2240.00 |
| TO REPLACE LOGO, EMBLEM, T/GATE PNL & GARNISH, W/STRIP, REAR BUMPER, EXTN |       |                   |     |                           |            |       |         |
| BUMPER, SIDE BRACKETS, BUMPER CLIPS, LH RFLTR LAMP, RHR FOG LAMP,         |       |                   |     |                           |            |       |         |
| LH/RH CORE BPR, REINFORCEMENT & BRACKET 1PC, TRIM RR END, LH & RH WHEEL   |       |                   |     |                           |            |       |         |
| ARCH MLDG. -TO CUT & WELD REAR END PANEL                                  |       |                   |     |                           |            |       |         |
| STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS                 |       |                   |     |                           |            |       |         |
| E PNT98000  |       |                   |     |                           |            |       | 1650.00 |
| SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS                            |       |                   |     |                           |            |       |         |
| (TAILGATE PNL, UPPER REAR BUMPER, REAR END PANEL)                         |       |                   |     |                           |            |       |         |
| E PNT88000  |       |                   |     |                           |            |       | 80.00   |
| TO CHECK, TEST, REFIT REVERSE SENSOR                                      |       |                   |     |                           |            |       |         |
| E PNT88000  |       |                   |     |                           |            |       | 220.00  |
| TO SUPPLY ONE SET REVERSE SENSORS   |       |                   |     |                           |            |       |         |
| M SUNDRY  |       |                   |     |                           |            |       | 50.00   |
| TO SUPPLY REAR LICENSE PLATE WITH FRAME                                   |       |                   |     |                           |            |       |         |
| M SUNDRY  |       |                   |     |                           |            |       | 100.00  |

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

## CYCLE &amp; CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722



Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address      | Owner Name & Vehicle Info                  |
|-----------------------------|--|
| Mr Chua Tian Seong          | Cust No/Name /Mr Chua Tian Seong           |
| 146 Rivervale Drive         | Reg No/Reg Date SNF5377H / 01/06/2022      |
| #06-505                     | Date In/Mileage 24/09/2024/ 57309          |
| Singapore 540146            | Chassis No JMAXTGK1WNZ000146               |
| Contact No Mobile: 96641766 | Engine No 4B40JL4952                       |
|                             | Make/Model MIT/ECLIPSE CROSS CLASSIC (T04) |
|                             | Colour/Trim W85 WHITE DIAMOND / BK BLACK   |


| Account No                                   | Terms | Date/Time Printed | CSE        | Operator                  | WIP No  |
|--|-------|-------------------|------------|---------------------------|---------|
| CTP00040                                     | Cash  | 07/10/2024/ 17:09 | REN        | 979 / Renemer Ramirez Bag | 26917   |
| Description of Goods / Services              |       | Qty               | Unit Price | Disc%                     | Amount  |
| TO APPLY GLASS SEALANT ON NEW TAILGATE GLASS |       |                   |            |                           |         |
| M SUNDRY                                     |       |                   |            |                           | 200.00  |
| TO APPLY BODY SEALANT ON NEW PANELS          |       |                   |            |                           |         |
| M SUNDRY                                     |       |                   |            |                           | 200.00  |
| TO APPLY ANTI-CORROSION ON AFFECTED AREAS    |       |                   |            |                           |         |
| M SUNDRY                                     |       |                   |            |                           | 50.00   |
| TO SUPPLY MIVEC EMBLEM                       |       |                   |            |                           |         |
| M SUNDRY                                     |       |                   |            |                           | 50.00   |
| TO SUUPLY C&C BADGE                          |       |                   |            |                           |         |
| M SUNDRY                                     |       |                   |            |                           | 20.00   |
| SUNDRIES                                     |       |                   |            |                           |         |
| Z TEXT                                       |       |                   |            |                           |         |
| FINALIZATION                                 |       |                   |            |                           |         |
| NO. OF TOTAL REPAIR DAYS - 7 DAYS            |       |                   |            |                           |         |
| ATTENTION TO MR. MARCUS CHUA (LKK)           |       |                   |            |                           |         |
| M DAM, TAILGATE, LWR                         |       | 1.00              | 13.00      | 00.00                     | 13.00   |
| M SPACER, TAILGATE                           |       | 4.00              | 8.00       | 00.00                     | 32.00   |
| M STOPPER, WINDSHIELD GLASS                  |       | 2.00              | 4.00       | 00.00                     | 8.00    |
| M FASTENER, WINDSHIELD                       |       | 4.00              | 8.00       | 00.00                     | 32.00   |
| M MARK, THREE-DIA                            |       | 1.00              | 64.00      | 00.00                     | 64.00   |
| M MARK, ECLIPSE                              |       | 1.00              | 71.00      | 00.00                     | 71.00   |
| M MARK, CROSS                                |       | 1.00              | 53.00      | 00.00                     | 53.00   |
| M GARNISH, TAILGATE                          |       | 1.00              | 779.00     | 00.00                     | 779.00  |
| M PANEL ASSY, TAILGATE                       |       | 1.00              | 1099.00    | 00.00                     | 1099.00 |
| M W/STRIP, TAILGATE OPENING                  |       | 1.00              | 198.00     | 00.00                     | 198.00  |
| M FACE, RR BUMPER                            |       | 1.00              | 675.00     | 00.00                     | 675.00  |
| M EXTENSION, RR BUMPER                       |       | 1.00              | 197.00     | 00.00                     | 197.00  |
| M BRKT, R/BMPR FACE SIDE, LH                 |       | 1.00              | 46.00      | 00.00                     | 46.00   |
| M BRKT, R/BMPR FACE SIDE, RH                 |       | 1.00              | 46.00      | 00.00                     | 46.00   |
| M CLIP, ENG ROOM COVER                       |       | 5.00              | 2.00       | 00.00                     | 10.00   |
| M CLIP, FR BUMPER                            |       | 5.00              | 4.00       | 00.00                     | 20.00   |
| M REFLECTOR, TAIL LAMP, LH                   |       | 1.00              | 73.00      | 00.00                     | 73.00   |
| M LAMP ASSY, FOG, RR RH                      |       | 1.00              | 250.00     | 00.00                     | 250.00  |

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

## CYCLE &amp; CARRIAGE AUTOMOTIVE PTE LIMITED

## Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722



Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address      | Owner Name & Vehicle Info                  |
|-----------------------------|--|
| Mr Chua Tian Seong          | Cust No/Name /Mr Chua Tian Seong           |
| 146 Rivervale Drive         | Reg No/Reg Date SNF5377H / 01/06/2022      |
| #06-505                     | Date In/Mileage 24/09/2024/ 57309          |
| Singapore 540146            | Chassis No JMAXTGK1WNZ000146               |
| Contact No Mobile: 96641766 | Engine No 4B40JL4952                       |
|                             | Make/Model MIT/ECLIPSE CROSS CLASSIC (T04) |
|                             | Colour/Trim W85 WHITE DIAMOND / BK BLACK   |

| Account No                      | Terms | Date/Time Printed | CSE        | Operator                  | WIP No |
|---------------------------------|-------|-------------------|------------|---------------------------|--------|
| CTP00040                        | Cash  | 07/10/2024/ 17:09 | REN        | 979 / Renemer Ramirez Bag | 26917  |
| Description of Goods / Services |       | Qty               | Unit Price | Disc%                     | Amount |
| M CORE,RR BUMPER LH             |       | 1.00              | 36.00      | 00.00                     | 36.00  |
| M CORE,RR BUMPER RH             |       | 1.00              | 36.00      | 00.00                     | 36.00  |
| M REINFORCEMENT,RR BUMPER       |       | 1.00              | 521.00     | 00.00                     | 521.00 |
| M BRACKET,RR REINFORCEMENT      |       | 1.00              | 30.00      | 00.00                     | 30.00  |
| M PANEL,RR END                  |       | 1.00              | 486.00     | 00.00                     | 486.00 |
| M TRIM,RR END                   |       | 1.00              | 124.00     | 00.00                     | 124.00 |
| M MOULDING,RR WHEEL ARCH,LH     |       | 1.00              | 162.00     | 00.00                     | 162.00 |
| M MOULDING,RR WHEEL ARCH,RH     |       | 1.00              | 162.00     | 00.00                     | 162.00 |

Estimate

Confirm &amp; accepted by

9% GST on **Nett** **11,403.00**  
**11403.00** **1026.27**  
**Total Payable** **12,429.27**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.