

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CD/111 24090455/40

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNF 5377H

at Workshop m/s C & C Ubi

of 10.30am

Insured: GRM 5175D

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: \$133k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

939J
Vehicle: IN / OUT

Date: _____ Person Contacted: L 1A 525267

Veh No: SNF 5377H Yr Regn: 01/106/22

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: mit solipe cos c.c 1499

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 57310 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMAXTGKIWN 2000146

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/70R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 24/09/24 D.O.I. 1/10/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction dep 16h

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	939J
Vehicle Details	
Vehicle No.:	SNF5377H
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Oct 2024
Vehicle Make:	MITSUBISHI
Vehicle Model:	ECLIPSE CROSS 1.5 CVT 2WD (M-LINE)
Primary Colour:	White
Manufacturing Year:	2021
Engine No.:	4B40JL4952
Chassis No.:	JMAXTGK1WNZ000146
Maximum Power Output:	120.0 kW (160 bhp)
Open Market Value:	\$15,705.00
Original Registration Date:	01 Jun 2022
First Registration Date:	01 Jun 2022
Transfer Count:	0
Actual ARF Paid:	\$15,705.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 May 2032
PARF Rebate Amount:	\$11,778.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2032
COE Category:	B - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$95,889.00
COE Rebate Amount:	\$73,489.00
Total Rebate Amount:	\$85,267.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 01 Oct 2024

OK

HomeUsed CarsListing

All Category

🔍

Filter

1





Search

📄 Save Search

🗑️

2022 X

2 Vehicles

Car Make	Car Model	Price Range	Depreciation	2022	Mileage	
	Mitsubishi Eclipse Cross 1.5A Highline	\$135,800 Instl. \$1,328 /mth	 \$17,280 /yr 1,499 cc 81 Owner	09-Feb-2022 (7yrs 4mths COE left)	43,000 km	🔖
<p>1 owner only. Low depreciation. 5 years Agent warranty. Well maintained paintwork. Accident free. No repair needed. White color exterior. High loan approval rate with low interest rate. High trade in offer. Buy with peace of mind. Must view the car to appreciate. Call us for a viewing now!</p> <div><div>🛒 BuySafe</div><div>🔖 Compare</div></div> <p>Posted 08-Sep-2024</p>						
	Mitsubishi Eclipse Cross 1.5A Highline	\$138,000 Instl. \$1,350 /mth	 \$16,940 /yr 1,499 cc 81 Owner	11-Mar-2022 (7yrs 5mths COE left)	36,000 km	🔖
<p>1 lady owner, genuine low mileage, car service by agent, accident free, no agent or consignment.</p> <div><div></div><div>🔖 Compare</div></div> <p>Posted 08-Aug-2024</p>						

PREMIUM AD

DIRECT OWNER

For old advertisements, view Expired ads

📄 Save Search

2 Vehicles

Car Make	Car Model	Price Range	Depreciation	2022	Mileage	
----------	-----------	-------------	--------------	------	---------	--

< Prev

1

Next >

20 results/page



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

not about
near
1/10/24
the phone
7 days
MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Chua Tian Seong 146 Rivervale Drive #06-505 Singapore 540146 Contact No Mobile: 96641766	Cust No/Name /Mr Chua Tian Seong Reg No/Reg Date SNF5377H / 01/06/2022 Date In/Mileage 24/09/2024/ 57309 Chassis No JMAXTGK1WNZ000146 Engine No 4B40JL4952 Make/Model MIT/ECLIPSE CROSS CLASSIC (T04) Colour/Trim W85 WHITE DIAMOND / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	25/09/2024/ 13:52	REN	979 / Renemer Ramirez Bag	26917
Description of Goods / Services				Qty	Unit Price Disc% Amount
Z TEXT					
ACCIDENT ON 24/09/2024 ALONG MANDAI ROAD					
OWNER CLAIMING THIRD PARTY CLAIM					
REQUIRED REPLACEMENT VEHICLE					
TP#: GBM5175D TP INS: INDIA INT'L INSURANCE					280.00
A 10028901					
TO CARRY OUT DIAGNOSTIC CHECK ON MUT AND CLEAR TROUBLE CODE					100.00
A 90000001					
TO CHECK WIRING AND ELECTRICAL SYSTEM					320.00
E PNT88000					
TO REMOVE & REPLACE TAILGATE GLASS,DAMS,SPACERS & FASTENERS					280.00
E PNT88000					
TO INSTALL RIKECOOL SOLAR FILM ON NEW TAILGATE GLASS					640.00
E PNT88000					
TO TRANSFER TAILGATE COMPONENTS & MECHANISM					640.00
E PNT88000					
TO REMOVE & RE-INSTALL TRIMS,CARPETS,FLOOR BOARDS TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS					4480.00
E PNT88000					
TO REPLACE LOGO,EMBLEM,T/GATE PNL & GARNISH,LH/RH GAS SPRING,LATCH, LOCK HANDLE,STRIKER,T/GATE LWR TRIM,W/STRIP,PLATE LAMPS,OTR & INR TAILLAMPS,REAR BUMPER,EXTN BPR,SIDE BRACKETS,CLIPS,LH RFLTR LAMP, RHR FOG LAMP,LH/RH CORE BPR,REINFORCEMENT & BRACKET,ANTENNA,BUZZER,ETC -TO CUT & WELD REAR END PANEL -TO REPAIR REAR FLOOR STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS					2750.00
E PNT88000					
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS (TAILGATE PNL,UPPER REAR BUMPER,REAR END PANEL,REAR FLOOR)					100.00
E PNT88000					
TO CHECK,TEST,REFIT REVERSE SENSOR					220.00
E PNT88000					
TO SUPPLY ONE SET REVERSE SENSORS					640.00
E PNT88000					

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
Mr Chua Tian Seong 146 Rivervale Drive #06-505 Singapore 540146 Contact No Mobile: 96641766	Cust No/Name /Mr Chua Tian Seong Reg No/Reg Date SNF5377H / 01/06/2022 Date In/Mileage 24/09/2024/ 57309 Chassis No JMAXTGK1WNZ000146 Engine No 4B40JL4952 Make/Model MIT/ECLIPSE CROSS CLASSIC (T04) Colour/Trim W85 WHITE DIAMOND / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00040	Cash	25/09/2024/ 13:52	REN	979 / Renemer Ramirez Bag	26917		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
TO REMOVE & REPLACE EXHAUST MUFFLER							50.00
M SUNDRY							100.00
TO SUPPLY REAR LICENSE PLATE WITH FRAME							300.00
M SUNDRY							300.00
TO APPLY GLASS SEALANT ON NEW TAILGATE GLASS							50.00
M SUNDRY							50.00
TO APPLY BODY SEALANT ON NEW PANELS							50.00
M SUNDRY							50.00
TO APPLY ANTI-CORROSION ON AFFECTED AREAS							50.00
M SUNDRY							50.00
TO SUPPLY MIVEC EMBLEM							50.00
M SUNDRY							50.00
TO SUPPLY C&C BADGE							606.00
M SUNDRY							13.00
SUNDRIES				1.00	606.00	00.00	32.00
M GLASS, TAILGATE WINDOW				1.00	13.00	00.00	8.00
M DAM, TAILGATE, LWR				4.00	8.00	00.00	32.00
M SPACER, TAILGATE				2.00	4.00	00.00	64.00
M STOPPER, WINDSHIELD GLASS				4.00	8.00	00.00	71.00
M FASTENER, WINDSHIELD				1.00	64.00	00.00	53.00
M MARK, THREE-DIA				1.00	71.00	00.00	779.00
M MARK, ECLIPSE				1.00	53.00	00.00	1099.00
M MARK, CROSS				1.00	779.00	00.00	156.00
M GARNISH, TAILGATE				1.00	1099.00	00.00	156.00
M PANEL ASSY, TAILGATE				1.00	156.00	00.00	213.00
M GAS SPRING, TAILGATE, LH				1.00	156.00	00.00	234.00
M GAS SPRING, TAILGATE, RH				1.00	213.00	00.00	21.00
M HANDLE, TAILGATE LOCK RLSE				1.00	234.00	00.00	421.00
M LATCH, TAILGATE				1.00	21.00	00.00	198.00
M STRIKER, TAILGATE LATCH				1.00	421.00	00.00	36.00
M TRIM, TAILGATE, LWR				1.00	198.00	00.00	
M W/STRIP, TAILGATE OPENING				2.00	36.00	00.00	
M LAMP ASSY, LICENSE PLATE							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Chua Tian Seong 146 Rivervale Drive #06-505 Singapore 540146 Contact No Mobile: 96641766	Cust No/Name /Mr Chua Tian Seong Reg No/Reg Date SNF5377H / 01/06/2022 Date In/Mileage 24/09/2024/ 57309 Chassis No JMAXTGK1WNZ000146 Engine No 4B40JL4952 Make/Model MIT/ECLIPSE CROSS CLASSIC (T04) Colour/Trim W85 WHITE DIAMOND / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	25/09/2024/ 13:52	REN	979 / Renemer Ramirez Bag	26917
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M OTR LAMP ASSY,COMB,RR LH		1.00	552.00	00.00	552.00
M OTR LAMP ASSY,COMB,RR RH		1.00	552.00	00.00	552.00
M INR LAMP ASSY,TAIL,LH		1.00	471.00	00.00	471.00
M INR LAMP ASSY,TAIL,RH		1.00	471.00	00.00	471.00
M FACE,RR BUMPER		1.00	675.00	00.00	675.00
M EXTENSION,RR BUMPER		1.00	197.00	00.00	197.00
M BRKT,R/BMPR FACE SIDE,LH		1.00	46.00	00.00	46.00
M BRKT,R/BMPR FACE SIDE,RH		1.00	46.00	00.00	46.00
M CLIP,ENG ROOM COVER		5.00	2.00	00.00	10.00
M CLIP,FR BUMPER		5.00	4.00	00.00	20.00
M REFLECTOR,TAIL LAMP,LH		1.00	73.00	00.00	73.00
M LAMP ASSY,FOG,RR RH		1.00	250.00	00.00	250.00
M CORE,RR BUMPER LH		1.00	36.00	00.00	36.00
M CORE,RR BUMPER RH		1.00	36.00	00.00	36.00
M REINFORCEMENT,RR BUMPER		1.00	521.00	00.00	521.00
M BRACKET,RR REINFORCEMENT		2.00	30.00	00.00	60.00
M BUZZER,KEYLESS OPERATIO,RR		1.00	96.00	00.00	96.00
M ANT,KEYLESS OPERATION,RR		1.00	102.00	00.00	102.00
M PANEL,RR END		1.00	486.00	00.00	486.00
M TRIM,RR END		1.00	124.00	00.00	124.00
M LID,CARGO FLOOR BOX		1.00	265.00	00.00	265.00
M BOX,CARGO FLOOR,LH		1.00	200.00	00.00	200.00
M BOX,CARGO FLOOR,RH		1.00	200.00	00.00	200.00
M TRIM,QTR,LWR LH		1.00	287.00	00.00	287.00
M TRIM,QTR,LWR RH		1.00	287.00	00.00	287.00
M MOULDING,RR WHEEL ARCH,LH		1.00	162.00	00.00	162.00
M MOULDING,RR WHEEL ARCH,RH		1.00	162.00	00.00	162.00
M SHIELD,RR WHEEL,RR LH		1.00	41.00	00.00	41.00
M SHIELD,RR WHEEL,RR RH		1.00	41.00	00.00	41.00
M MUFFLER,EXHAUST MAIN		1.00	571.00	00.00	571.00

Estimate

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Authorized signatory and company stamp

Acknowledged by Repairer

Signature

Nett 22,618.00

9% GST on 22618.00 2035.62

Total Payable 24,653.62

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.