



*Not Authorised  
in  
works  
25/9/24  
maybe TOTAL LOSS*

**QUOTATION**

NO. : 47760

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD  
CHARTIS BUILDING  
78 SHENTON WAY  
#07-16  
SINGAPORE 079120  
ATTN: MOTOR CLAIMS DEPT

DATE : 23/09/2024  
CLAIM NO. : 12598  
POLICY NO. : MC/01213132/01

FROM : RAYMOND

VEHICLE NO. : FBK5930B  
MAKE/MODEL : SUZ / UH200AL5

(Page 1 of 5)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCE HANDLE - (REPORTED BY MECHANIC)	Replace	1.00	\$23.00	23.00 X
2	BEARING STEERING CONE P/N: 44475 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$74.00	74.00 ✓
3	BEARING STEERING CONE (25X47X15) P/N: 65372 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	85.00 ✓
4	BELLY PAN - (REPORTED BY MECHANIC)	REPLACE	1.00	\$181.00	181.00 ✓
5	BOX FRONT (BLACK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$341.00	341.00 ✓
6	BOX REAR 45L (KKK) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$388.00	388.00 ?
7	BRACE, LEG SHIELD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$164.00	164.00 ✓
8	BRACKET UNDER FORK P/N: 65380 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$939.00	939.00 ✓
9	BRACKET BOX REAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$481.00	481.00 X

\*47760 \*



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>		<u>Amount</u>
10	CLIP (BLACK) P/N: 63231 - (REPORTED BY MECHANIC)	REPLACE	5.00	\$5.00	ner	25.00
11	COVER SHIELD, LEG FRONT (WHITE) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$81.00	me	81.00
12	COVER SHIELD, LEG FRONT (WHITE) P/N: 65363 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$458.00	me	458.00
13	COVER SIDE LOWER LH (GRAY) P/N: 63223 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$205.00	me	205.00
14	COVER SIDE LOWER RH (GRAY) P/N: 68137 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$205.00	cu?	205.00
15	COVER TAIL LH (WHITE) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$164.00	cu?	164.00
16	COVER, FRONT (WHITE) P/N: 65370 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$168.00	cu?	168.00
17	COVER, MUFFLER P/N: 65386 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$97.00	n	97.00 X
18	COVER, MUFFLER RR P/N: 68131 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$61.00	n	61.00 X
19	CUSHION P/N: 63225 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.00	?	12.00
20	CUSHION P/N: 65365 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.00	?	12.00
21	CUSHION P/N: 65368 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.00	?	12.00
22	CUSHION COVER P/N: 65387 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	?	5.00
23	CUSHION,FR BOX NO.3 P/N: 85177 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$8.00	ner	16.00
24	CUSHION,FR BOX NO.4 P/N: 85170 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$8.00	ner	16.00
25	CUSHION,FR BOX NO.5 P/N: 85171 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$8.00	ner	16.00

\*47760 \*



S/N	Description	Action	Qty	Unit Price	Amount
26	CUSHION,FR BOX NO.6 P/N: 85176 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$8.00	<i>ner</i> 16.00
27	CUSHION,FR PANEL LID NO.1 P/N: 85169 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	<i>Dye</i> 10.00
28	CUSHION,FRAME COVER UPR NO.2 P/N: 85166 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	<i>Dye</i> 6.00
29	DAMPER - (REPORTED BY MECHANIC)	REPLACE	4.00	\$5.00	<i>ner</i> 20.00
30	DAMPER ASSY, FRONT FORK LH P/N: 63238 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$944.00	<i>Buy</i> 944.00
31	EMBLEM "200" (GRAY/WHITE) - (REPORTED BY MECHANIC)	REPLACE	2.00	\$28.00	<i>ner</i> 56.00
32	EMBLEM (BURGSMAN) LOGO P/N: 61583 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$47.00	<i>ner</i> 94.00
33	EMBLEM, "S" P/N: 63216 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	<i>ner</i> 31.00
34	FENDER, FRONT (WHITE) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$183.00	<i>cut</i> 183.00
35	FOOTBOARD, LH (BLACK) P/N: 63224 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	<i>cut</i> 37.00
36	FORK FRONT RH ASSY P/N: 65371 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$944.00	? 944.00
37	FRONT BELLY PAN (GRAY) P/N: 63215 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$186.00	<i>cut</i> 186.00
38	HANDLE SEAT LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$186.00	<i>cut</i> 186.00
39	HANDLE SEAT RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$186.00	<i>n</i> 186.00 X
40	HEADLAMP ASSY P/N: 63228 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$559.00	<i>one</i> 559.00

\*47760 \*



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>		<u>Amount</u>
41	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	20.00	\$85.00	600	1,700.00
42	LAMP SIGNAL FRONT LH ASSY P/N: 63229 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$115.00	CRU	115.00
43	LAMP SIGNAL FRONT RH ASSY P/N: 63236 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$115.00	11	115.00 X
44	LEVER ASSY, REAR BRAKE P/N: 63218 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$48.00	CRU	48.00
45	LEVER, FRONT BRAKE P/N: 63226 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$61.00	CRU	61.00
46	LID INNER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$41.00	D.S	41.00
47	LID LH (BLACK) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	D.S	17.00
48	LID OUTER (BLACK) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$60.00	?	60.00
49	MAT FLOOR LH (BLACK) P/N: 70262 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$65.00	CRU	65.00
50	MAT FLOOR RH (BLACK) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$65.00	CRU	65.00
51	MIRROR ASSY RR VIEW LH P/N: 63217 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$68.00	BRO	68.00
52	MIRROR ASSY RR VIEW RH P/N: 63220 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$68.00	CRU	68.00
53	OBV TYPE B (12V) NEW P/N: 82490 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$341.00	?	341.00
54	PANEL METER LOWER (BLACK) P/N: 65385 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$100.00	CRU	100.00
55	REPAIR ON BODY ALIGNMENT - (REPORTED BY MECHANIC)	Repair	1.00	\$775.00	?	775.00

\*47760 \*



S/N	Description	Action	Qty	Unit Price	Amount
56	RUBER FLOOR MAT SET REAR-(dis-continued.) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$0.00	0.00
57	SEAL STEERING UPPER DUST P/N: 44470 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00
58	STAND MAIN - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00
59	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00	30.00 <sup>10</sup>
60	TRANSPORT CHARGES P/N: 07169		1.00	\$63.00	63.00
61	WINDSCREEN P/N: 63233 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,251.00	1,251.00

SUB TOTAL	\$12,721.00
GST @ 9 %	\$1,144.89
<b>GRAND TOTAL (SGD)</b>	<b>\$13,865.89</b>

**50% deposit required before ordering of parts.**

Validity: 30 days

For & on Behalf of  
**BAN HOCK HIN CO PTE LTD**

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

\*47760 \*

