



Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPT

VEHICLE NO. : FBK5930B
MAKE/MODEL : SUZ / UH200AL5

*Not Authorized
in
near
25/9/24*

maybe total loss

*1/5 @ 3100
5 days*

limit repair

QUOTATION

NO. : 47760

*MV 3800
LTA 658
NETT 3100*

DATE : 23/09/2024
CLAIM NO. : 12598
POLICY NO. : MC/01213132/01

FROM : RAYMOND

(Page 1 of 5)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCE HANDLE - (REPORTED BY MECHANIC)	Replace	1.00	\$23.00	23.00 X
2	BEARING STEERING CONE P/N: 44475 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$74.00	74.00 ✓
3	BEARING STEERING CONE (25X47X15) P/N: 65372 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	85.00 ✓
4	BELLY PAN - (REPORTED BY MECHANIC)	REPLACE	1.00	\$181.00	181.00 X
5	BOX FRONT (BLACK) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$341.00	341.00 ✓
6	BOX REAR 45L (KKK) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$388.00	388.00 X
7	BRACE, LEG SHIELD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$164.00	164.00 ✓
8	BRACKET UNDER FORK P/N: 65380 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$939.00	939.00 ✓
9	BRACKET BOX REAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$481.00	481.00 X

*47760 *



S/N	Description	Action	Qty	Unit Price	Amount
10	CLIP (BLACK) P/N: 63231 - (REPORTED BY MECHANIC)	REPLACE	5.00	\$5.00	<i>ner</i> 25.00 ✓
11	COVER SHIELD, LEG FRONT (WHITE) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$81.00	<i>SVC</i> 81.00 ✗
12	COVER SHIELD, LEG FRONT (WHITE) P/N: 65363 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$458.00	<i>one</i> 458.00 ✓
13	COVER SIDE LOWER LH (GRAY) P/N: 63223 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$205.00	<i>one</i> 205.00 ✓
14	COVER SIDE LOWER RH (GRAY) P/N: 68137 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$205.00	<i>SVC</i> 205.00 ✗
15	COVER TAIL LH (WHITE) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$164.00	<i>SVC</i> 164.00 ✗
16	COVER, FRONT (WHITE) P/N: 65370 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$168.00	<i>one</i> 168.00 ✓
17	COVER, MUFFLER P/N: 65386 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$97.00	<i>~</i> 97.00 ✗
18	COVER, MUFFLER RR P/N: 68131 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$61.00	<i>~</i> 61.00 ✗
19	CUSHION (1 /) P/N: 63225 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.00	<i>All</i> 12.00 ✓
20	CUSHION (2 /) P/N: 65365 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.00	<i>All</i> 12.00 ✓
21	CUSHION (3 /) P/N: 65368 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.00	<i>All</i> 12.00 ✓
22	CUSHION COVER (4 /) P/N: 65387 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	<i>All</i> 5.00 ✓
23	CUSHION,FR BOX NO.3 P/N: 85177 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$8.00	<i>ner</i> 16.00 ✓
24	CUSHION,FR BOX NO.4 P/N: 85170 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$8.00	<i>ner</i> 16.00 ✓
25	CUSHION,FR BOX NO.5 P/N: 85171 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$8.00	<i>ner</i> 16.00 ✓

*47760 *



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
26	CUSHION,FR BOX NO.6 P/N: 85176 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$8.00	net 16.00 ✓
27	CUSHION,FR PANEL LID NO.1 P/N: 85169 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	Dye 10.00 ✓
28	CUSHION,FRAME COVER UPR NO.2 P/N: 85166 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	Dye 6.00 ✓
29	DAMPER - (REPORTED BY MECHANIC)	REPLACE	4.00	\$5.00	net 20.00 ✓
30	DAMPER ASSY, FRONT FORK LH P/N: 63238 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$944.00	But 944.00 ✓
31	EMBLEM "200" (GRAY/WHITE) - (REPORTED BY MECHANIC)	REPLACE	2.00	\$28.00	SVC 56.00 ✗
32	EMBLEM (BURGSMAN) LOGO P/N: 61583 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$47.00	SVC 94.00 ✗
33	EMBLEM, "S" P/N: 63216 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	SVC 31.00 ✗
34	FENDER, FRONT (WHITE) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$183.00	cut 183.00 ✓
35	FOOTBOARD, LH (BLACK) P/N: 63224 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	SVC 37.00 ✗
36	FORK FRONT RH ASSY P/N: 65371 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$944.00	But 944.00 ✓
37	FRONT BELLY PAN (GRAY) P/N: 63215 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$186.00	SVC 186.00 ✗
38	HANDLE SEAT LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$186.00	SVC 186.00 ✗
39	HANDLE SEAT RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$186.00	net 186.00 ✗
40	HEADLAMP ASSY P/N: 63228 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$559.00	net 559.00 ✓

5230

*47760 *



S/N	Description	Action	Qty	Unit Price	Amount
41	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	20.00	\$85.00	600 1,700.00
42	LAMP SIGNAL FRONT LH ASSY P/N: 63229 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$115.00	one 115.00
43	LAMP SIGNAL FRONT RH ASSY P/N: 63236 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$115.00	1-1 115.00 X
44	LEVER ASSY, REAR BRAKE P/N: 63218 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$48.00	SVC 48.00
45	LEVER, FRONT BRAKE P/N: 63226 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$61.00	SVC 61.00
46	LID INNER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$41.00	DYS 41.00
47	LID LH (BLACK) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	DYS 17.00
48	LID OUTER (BLACK) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$60.00	PN 60.00 X
49	MAT FLOOR LH (BLACK) P/N: 70262 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$65.00	one 65.00
50	MAT FLOOR RH (BLACK) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$65.00	SVC 65.00
51	MIRROR ASSY RR VIEW LH P/N: 63217 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$68.00	BRO 68.00
52	MIRROR ASSY RR VIEW RH P/N: 63220 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$68.00	SU 68.00 X
53	OBU TYPE B (12V) NEW P/N: 82490 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$341.00	PN 341.00 X
54	PANEL METER LOWER (BLACK) P/N: 65385 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$100.00	one 100.00
55	REPAIR ON BODY ALIGNMENT - (REPORTED BY MECHANIC)	Repair	1.00	\$775.00	PN 775.00 X

*47760 *



S/N	Description	Action	Qty	Unit Price	Amount
56	RUBER FLOOR MAT SET REAR-(dis-continued.) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$0.00	0.00 X
57	SEAL STEERING UPPER DUST P/N: 44470 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00
58	STAND MAIN - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00 X
59	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00	30.00 X
60	TRANSPORT CHARGES P/N: 07169		1.00	\$63.00	63.00
61	WINDSCREEN P/N: 63233 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,251.00	1,251.00 X

SUB TOTAL	\$12,721.00
GST @ 9 %	\$1,144.89
GRAND TOTAL (SGD)	\$13,865.89

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-55684
102
5715.60
600
5715.60
292
4572.

*47760 *

