

NG SHING MECHANICAL

Business Reg. No: 34823200D

(Repair & Insurance Claim)

160 Sin Ming AutoCity, 160 Sin Ming Drive #06-21, Singapore 575722

Vehicle number :

SKA8091Z

Date of Accident :

2024/6/18

Accident along :

Queensway underpass

Parts

1	Front wing mirror housing	CM	1,694.40	✓
2	Front wing mirror outer cover	mir	62.60	✓
3	Front wing mirror signal lamp	CM	45.40	✓
4	Front wing mirror glass	CM	105.50	✓

Total parts 1,907.90
25% 476.98
1,430.93

Labour

1	Labour	300.00	801
2	Spray painting	300.00	801
3	Rewire	50.00	201

Total labour 650.00

Total repair cost 1,126.98

NOT Notified
C/Pay @ 1250p
Running After Paint
1 day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: