



FALCON-AIR

CHEW GEK ENG

C/O 176 SIN MING DRIVE #01-06/07  
SIN MING AUTOCARE  
575721

JARED TAY - 96314818  
Attn: MOTOR CLAIMS DEPT  
Tel: 93673150

*Not Notified*  
*61 Day @ 2350/-*  
*Resurvey After Rain*  
*5 days*

Estimate : ES000104  
Date : 20/09/2024  
Vehicle No. : SLP8631A  
Vehicle Model : SUBARU FORESTER 2.0XT CVT AWD SR  
Chassis No. : JF1SJGK85HG088207  
Accident Date : 18/09/2024  
Claim No. :  
Reference : TP - GEG AGT MS FIRST CAPITAL  
Policy No. : V5015559  
Page : 1 of 2

Item	Qty	Description	Unit Price S\$	Amount S\$
1.	1	TAILGATE LOGO	98.00	98.00 ✓
2.	1	TAILGATE EMBLEM SUBARU	95.00	95.00 ✓
3.	1	TAILGATE EMBLEM FORESTER XT	85.00	85.00 ✓
4.	1	REAR BUMPER	769.00	769.00 ✓
5.	1	REAR BUMPER SIDE RETAINER	38.00	38.00 X
6.	1	REAR BUMPER TOW COVER	28.00	28.00 ^
7.	1	REAR BUMPER REINFORCEMENT	420.00	420.00 ✓
8.	1	REAR EXHAUST MUFFLER	888.00	888.00 X
9.	2	REAR EXHAUST MUFFLER RUBBER	30.00	60.00 X
10.	1	REAR END PANEL	458.00	458.00 ✓
11.	1	REAR END PANEL TOP GARNISH	68.00	68.00 X
		Discount 10 %		-300.70
		SubTotal		2,706.30
12.	1	REAR END PANEL TOP GARNISH CLIP	60.00	60.00 X
13.	1	REAR BUMPER CLIP	60.00	60.00 ✓
14.	1	REAR BUMPER LOWER SPOILER	1,660.00	1,660.00 X
15.	1	REAR BUMPER LOWER SPOILER CLIP	60.00	60.00 X
16.	1	TO CHECK WIRING AND LIGHT SYSTEM	60.00	60.00 15

*201*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Continue to Next Page



FALCON - AIR

**CHEW GEK ENG**

C/O 176 SIN MING DRIVE #01-06/07  
SIN MING AUTOCARE  
575721

JARED TAY - 96314818  
Attn : MOTOR CLAIMS DEPT  
Tel : 93673150

**Estimate : ES000104**  
Date : 20/09/2024  
Vehicle No. : SLP8631A  
Vehicle Model : SUBARU FORESTER 2.0XT CVT AWD SR  
Chassis No. : JF1SJGK85HG088207  
Accident Date : 18/09/2024  
Claim No. :  
Reference : TP - GEG AGT MS FIRST CAPITAL  
Policy No. : V5015559  
Page : 2 of 2

Item	Qty	Description	Unit Price S\$	Amount S\$
17.	1	APPLY BODY SEALANT ON BODY PARTS	<i>na</i> 50.00	<i>3010</i> 50.00
18.	1	TO RUSTPROOF ACCIDENT DAMAGE AREA	<i>na</i> 50.00	<i>3010</i> 50.00
19.	1	TO REMOVE/REFIX EXHAUST SYSTEM	<i>na</i> 150.00	<i>X</i> 150.00
20.	1	TO REMOVE/REFIT REVERSE SENSOR INTO NEW BUMPER	100.00	<i>501</i> 100.00
21.	1	TO REMOVE NECESSARY PARTS, TO REPAIR INNER PANEL, CUT OUT ACCIDENT DAMAGE PANEL, REWELD PANEL, REPLACE DAMAGE PARTS AND ALIGN THE SAME	700.00	<i>6001</i> 700.00
22.	1	TO PUTTY/RESPRAY TAILGATE, REAR BUMPER, END PANEL	800.00	<i>6401</i> 800.00

SINGAPORE DOLLAR SEVEN THOUSAND THIRTY SEVEN AND CENTS THIRTY SEVEN ONLY

**Total S\$ 6,456.30**

Notes :

- All cheques should be crossed and made payable to FALCON-AIR AUTO SERVICES PTE LTD
- Goods sold are neither returnable nor refundable. Otherwise a cancellation fee of 20% on purchase price will be imposed.

**Accepted by**

FALCON - AIR AUTO SERVICES PTE LTD  
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110  
Website: www.falconair.com.sg Email: email@falconair.com.sg