

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	AUTO & GENERAL	INSURANCE (S) PL	Ref:	CS/AGI24090459/Unp3	
	(BUDGET DIRECT I 190 CLEMENCEAU		Date:	08/10/2024	
		PING CENTRE SINGAPORE 239924	Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNL 1905D	Veh. Inspected	SNQ 3414P	
	Policy No.	P11113189R00	Coverage	0	
	Claim No.	C10031829/JK	Excess	\$0.00	
	Assign From	JANICE KOH	Assign Date	25/09/2024	
2. Vehicle Details					
	Make & Model	HONDA CIVIC 1.0SE TURBO	C.C	998	
	Engine No.	P10A21011935	Year of Reg.	27/12/2017	
	Chassis No.	SHHFK6840HU011967	Colour	RED	
	Odometer	95756 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
٥.					
0.		Size	Make	Balance (mm)	
<u> </u>	R/H Front Tyre	Size 225/40R18	Make YOKOHAMA	Balance (mm)	
<u> </u>	R/H Front Tyre L/H Front Tyre			, ,	
_ 0 .	-	225/40R18	YOKOHAMA	6	
3 .	L/H Front Tyre	225/40R18 225/40R18	YOKOHAMA YOKOHAMA	6	
4.	L/H Front Tyre R/H Rear Tyre	225/40R18 225/40R18 225/40R18	YOKOHAMA YOKOHAMA YOKOHAMA	6 6 6	
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	225/40R18 225/40R18 225/40R18 225/40R18	YOKOHAMA YOKOHAMA YOKOHAMA YOKOHAMA TOKOHAMA	6 6 6	
4. THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	225/40R18 225/40R18 225/40R18 225/40R18 225/40R18 Description of the company of	YOKOHAMA YOKOHAMA YOKOHAMA YOKOHAMA TOKOHAMA	6 6 6	
4. THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINI	225/40R18 225/40R18 225/40R18 225/40R18 225/40R18 Description of the company of	YOKOHAMA YOKOHAMA YOKOHAMA YOKOHAMA Of Damages	6 6 6	
4. THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINI	225/40R18 225/40R18 225/40R18 225/40R18 Pescription of ED DAMAGES AT THE REAR PORTIONS.	YOKOHAMA YOKOHAMA YOKOHAMA YOKOHAMA Of Damages	6 6 6	
4. THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINI IAGES SEE DETAILS	225/40R18 225/40R18 225/40R18 225/40R18 Description of ED DAMAGES AT THE REAR PORTIONS General Interpretation of the control	YOKOHAMA YOKOHAMA YOKOHAMA YOKOHAMA TOKOHAMA YOKOHAMA TOKOHAMA TOKOHAMA TOKOHAMA TOKOHAMA TOKOHAMA TOKOHAMA	6 6 6 6	
4. THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINI AGES SEE DETAILS Accident Date	225/40R18 225/40R18 225/40R18 225/40R18 Description of the second of th	YOKOHAMA YOKOHAMA YOKOHAMA YOKOHAMA Of Damages N. formation Inspection Date	6 6 6 6	
4. THE DAM 5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINI MAGES SEE DETAILS Accident Date Survey held at	225/40R18 225/40R18 225/40R18 225/40R18 Description of the second of th	YOKOHAMA YOKOHAMA YOKOHAMA YOKOHAMA YOKOHAMA TOTO Damages N. formation Inspection Date arks JUDICE" BASIS.	6 6 6 6	

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days