

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

BUDGET DIRECT INSURANCE

190 Clemenceau Avenue

#03-01

Singapore Shopping Centre

Singapore 079120

ATTN : Motor Claim Department

Your Ref No: : SNL 1905 D

Claim Type : THIRD PARTY

Accident Date : 23/09/2024

Estimate No. : E24090286

Date : 26/09/2024

Veh Reg No : SNQ 3414 P

Make / Model : HONDA CIVIC 1.0SE
TURBO CVT

Chassis No. : SHHFK6840HU011967

Engine No. : P10A21011935

Reg. Date : 27/12/2017

Not Authorised
meas
26/9/24
2/s \$5600
4 days

Estimate Repair Cost for Vehicle No. : SNQ 3414 P

S/N	Description	Quantity	Unit	Price	Amount
LIST PRICE				SS	SS
1	Rear Boot Lock	1	PCS	2204.90	2204.90 ✓
2	Rear Boot Lock Catch	1	PCS	220.90	220.90 X
3	Rear Boot Lock Rubber	1	PCS	39.00	39.00 X
4	Rear Boot Emblem	1	PCS	189.60	189.60 ✓
5	Rear Boot Centre Logo	1	PCS	99.20	99.20 ✓
6	Rear Boot Inner Cover Board	1	PCS	95.20	95.20 X
7	Rear Boot S/Absorber	1	PCS	446.30	446.30 q
8	Rear Boot Centre Garnish	2	PCS	129.70	259.40
9	Rear Boot Lamp - LH	1	PCS	687.20	687.20 ✓
10	Rear Taillamp	2	PCS	302.00	302.00 X
11	Rear Taillamp Clip	2	PCS	754.10	1508.20 1pc
12	Rear End Panel	1	PCS	6.50	13.00 X
13	Rear End Panel Top Garnish	1	PCS	719.40	719.40 X
14	Rear Bumper	1	PCS	149.20	149.20 X
15	Rear Bumper Side Retainer	2	PCS	2890.00	2890.00 ✓
16	Rear Boot Centre Logo	1	PCS	38.50	77.00 X
17	Rear Bumper Reinforcement	1	PCS	32.60	32.60 X
18	Rear Bumper Reinforcement Bracket	1	PCS	428.80	428.80 ✓
19	Rear Bumper Lower Spoiler	2	PCS	112.80	225.60 ✓
20	Rear Bumper Centre Garnish	1	PCS	1490.20	1490.20 ✓
21	Rear Bumper Side Garnish - RH	1	PCS	160.50	160.50 ✓
22	Rear Bumper Sensor	1	PCS	398.40	398.40 X
23	Rear Bumper Lower Clip	2	PCS	274.40	548.80 X
24	Rear Bumper Lower Clip	4	PCS	5.50	22.00 ✓

TOTAL PARTS :	13207.40
20% DISCOUNT 10% :	1320.74
SUB-TOTAL :	11886.66

S/N Description

SPECIAL NETT

S/N	Description	Quantity	Unit	Price	Amount
				SS	SS
1	Rear Bumper Top Chrome Plate	1	PCS	-	750.00 250
2	Rear Windscreen Gum Sealant	1	PCS	-	80.00 40
3	Rear Number Plate	1	PCS	-	100.00 40
4	Rear Reverse Camera	1	PCS	-	450.00 X

TOTAL SPECIAL NETT :	1380.00
----------------------	---------

FOCUS AUTO PTE LTD
NO. 1 KAKI BUKIT AVENUE 6 #02-48/50
AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

BUDGET DIRECT INSURANCE

190 Clemenceau Avenue
#03-01

Singapore Shopping Centre
Singapore 079120

ATTN : Motor Claim Department
Your Ref No: : **SNL 1905 D**
Claim Type : THIRD PARTY
Accident Date : 23/09/2024

Estimate No. : E24090286

Date : 26/09/2024

Veh Reg No : **SNQ 3414 P**

Make / Model : HONDA CIVIC 1.0SE
TURBO CVT

Chassis No. : SHHFK6840HU011967

Engine No. : P10A21011935

Reg. Date : 27/12/2017

Estimate Repair Cost for Vehicle No. : SNQ 3414 P

LABOUR CHARGES

- 1 Sundries
- 2 To Panel Beating
- 3 To Check Wiring
- 4 To Rust Proofing
- 5 To Remove & Refix Rear Windscreen
- 6 To Remove & Refix Bumper Sensor
- 7 To Spray Painting

<u>SS</u>	<u>SS</u>
11	30.00 X
	1000.00 550
	80.00 20
	80.00 30
	160.00 120
	80.00 30
	900.00 750

TOTAL LABOUR :	2330.00
GRAND TOTAL :	15596.66

FOR FOCUS AUTO PTE LTD

Jenny Koh
Claims Executive
HP: 8135 9800

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-6471.1
202
5176.88
330
1500
7006.88
202
5608