



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SDA680A NISSAN SERENA

No	Qty	Parts Description	Estimated Parts Price	
1	1	Front bumper <i>Delint</i>	\$ 920.60	✓
2	1	Bumper bracket <i>new</i>	\$ 180.00	+
3	1	Headlight-left (completed set) <i>cancel</i>	\$ 1,985.30	✓
4	1	Headlight -right (completed set) <i>cancel</i>	\$ 1,985.30	✓
5	1	Sponge <i>cancel</i>	\$ 180.00	✓
6	1	Tow cover <i>new</i>	\$ 70.00	+
7	2	Rear bumper sensor <i>new</i>	\$ 400.00	+
8	1	Reinforcement <i>Delint</i>	\$ 710.20	—
9	1	Pedestrian sensor <i>new</i>	\$ 280.00	+
10	1	Front bonnet <i>Delint</i>	\$ 950.40	✓
11	2	Bonnet absorber <i>new</i>	\$ 400.00	+
12	1	Middle Chrome whole set with linning together <i>cancel</i>	\$ 891.60	✓
13	1	Bumper lower linning 1 set <i>cancel</i>	\$ 210.00	✓
14	1	Fog lamp-left <i>new</i>	\$ 750.00	+
15	1	Fog lamp-right <i>new</i>	\$ 750.00	+
16	2	Airdust segment <i>Delint</i>	\$ 360.00	✓
17	1	Horn <i>new</i>	\$ 180.00	+
18	1	Bonnet lock assy <i>Delint</i>	\$ 280.00	✓
19	1	ABS Pump ws module -after accident abs light on <i>new</i>	\$ 1,500.00	+
20	1	Lower grille with number plate base <i>Delint</i>	\$ 220.00	—
Sub-total Parts			\$ 13,203.40	



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SDA680A NISSAN SERENA

No	Qty	Parts Description	Estimated Parts Price	
<u>Special Nett Items</u>				
1	10	Bumper clips <i>new</i>	\$ 80.00	30
2	10	Middle chrome clips <i>new</i>	\$ 80.00	30
3	6	Air duct clips <i>new</i>	\$ 60.00	30
4	10	Sensor cable clips <i>new</i>	\$ 60.00	+
5	8	Top cover clips <i>new</i>	\$ 80.00	+
6	10	Lower tray clips <i>new</i>	\$ 80.00	+
7	1	Rear no plate with garnish <i>new</i>	\$ 80.00	+
8	1	Coolant and gas usage <i>new</i>	\$ 90.00	+
Sub total special nett			\$ 610.00	



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SDA680A NISSAN SERENA

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,200.00 500
2	To putty and spray painting rear portion.	\$ 1,200.00 400
3	To check front lighting and wiring.	\$ 60.00 30
4	To remove and install front bonnet lock mechanism.	\$ 80.00 +
5	To remove & install lower tray trim cover to facilitate the repair.	\$ 80.00 +
6	To apply anti rust proofing to rear affected area	\$ 200.00 +
7	To remove and install front bumper reverse sensor.	\$ 80.00 50
8	Water test	\$ 100.00 +
9	To check radiator fountioning, coolant and gas level etc	\$ 80.00 +
10	Carry out diagnosis check including cleaning accident fault code	\$ 120.00 60
11	ABS pump module coding	\$ 350.00 +
12	Labour to remove abs pump, check and replace parts	\$ 150.00 +
Total labour :		\$ 3,700.00

Adrian L
1/530/09/24
04 Days