

FASTECH AUTO PTE LTD  
1 Kaki Bukit Ave 6 #01-48 Autobay  
Singapore 417883  
Tel No: 67452063/ 67467158 Fax No: 67458520  
Tax Reg No : 200006262D

not Authorized  
Mr  
Moran  
30/9/24  
2/s \$ 3900  
Alph. After repair  
3 days.

VEHICLE No: HJA 6646

|      |                                   |         |      |                     |
|------|-----------------------------------|---------|------|---------------------|
| 1PC  | REAR WINDSCREEN MOULDING          | neu     |      | \$110.00 ✓          |
| 1PC  | TAILGATE                          | 20/30.4 | 1680 | \$1,699.00 ✓        |
| 1PC  | TAILGATE INNER LOCK               | Damage  |      | \$199.80 ✓          |
| 1PC  | TAILGATE LOCK STRIKER             | su      |      | \$66.00 X           |
| 1PC  | TAILGATE INNER TRIM BOARD         | 11      |      | \$435.00 X          |
| 1SET | TAILGATE INNER TRIM BOARD CLIPS   | 11      |      | \$50.00 X           |
| 1PC  | TAILGATE WEATHERSTRIP             | su      |      | \$288.00 X          |
| 1PC  | REAR BUMPER                       | 20/30.1 | 1100 | \$1,480.00 ✓        |
| 1PC  | REAR BUMPER SIDE BLACK GARNISH LH | Damage  | 215  | \$470.20 ✓          |
| 1SET | REAR BUMPER CLIPS                 | neu     |      | \$50.00 ✓           |
| 1PC  | REAR BUMPER INNER BRACKET         | cro     |      | \$40.00 ✓           |
| 1PC  | REAR END PANEL                    | 11      |      | \$665.20 X          |
| 1PC  | REAR END PANEL TOP GARNISH        | 11      |      | \$341.10 X          |
| 2PCS | TAILLAMPS @\$650.00               | 11      |      | \$1,300.00 X        |
|      |                                   |         |      | \$7,194.30          |
|      |                                   |         |      | LESS 10% \$6,474.87 |

S.NETT

|      |                                             |     |                |
|------|---------------------------------------------|-----|----------------|
| 1PC  | REAR WINDSCREEN SEALANT                     | neu | \$50.00 40 S/N |
| 1PC  | REAR WINDSCREEN INNER SEAL                  | neu | \$50.00 20 "   |
| 1PC  | REAR END PANEL SEALANT                      | 11  | \$50.00 X      |
| 1SET | REAR BUMPER REVERSE SENSOR                  | cro | \$280.00 200 " |
| 1SET | REAR BUMPER 'JOHOR BAHRU- SINGAPORE STICKER | neu | \$250.00 150 " |
| 1SET | REAR FLOOR PANEL INSULATOR                  | 11  | \$120.00 X     |

|                                           |                |
|-------------------------------------------|----------------|
| TO CEHCK WIRING                           | \$50.00 20     |
| TO DISMANTLE & REPLACED REVERSE SENSOR    | \$80.00 30     |
| TO DISMANTLE & REFX REAR WINDSCREEN       | \$150.00 120   |
| TO TRANSFER TAILGATE MECHANISM            | \$100.00 60    |
| TO DISMANTLE & REFX CUSHION UPHOLSTERY    | \$120.00 50    |
| TO SPRAY RUST PROOFING                    | \$100.00 30    |
| LABOUR FOR PANEL BEATING & REPLACED PARTS | \$800.00 550   |
| TO PUTTY & SPRAY PAINTING                 | \$1,000.00 600 |
| TOTAL                                     | \$9,674.87     |

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P. 3394.80  
102  
3055.32  
410  
1460  
4525.32