

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0648/2024/KS
DATE : 25-Sep-24
WIP : 28918

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/9/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR VICKRUM MUTHSAM Y P
ADDRESS : 24 MUGLISTON
SINGAPORE 437728

TELEPHONE : HP +65 96908217
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800080628-05
VEHICLE NO : **SDB 9330 E**
MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC
MODEL YEAR : 12/7/2018
ENGINE NO : CVK 061246
CHASSIS NO : WAUZZZF41JA165172
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Aug-24
PLACE OF ACCIDENT : JUNCTION AT PAYA LEBAR ROAD. (UNDER PIE FLYOVER)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SDB 9330 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	350.00	
2	TO DISMANTLE AND RENEW LHS FRONT FENDER. TO REPAIR LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,750.00	
3	TO RESPRAY LHS FRONT FENDER AND LHS SILL PANEL.	\$	1,750.00	
4	TO CARRY OUT CHIP TREATMENT AND SEALANT WORK ON LHS SILL PANEL.	S/N \$	480.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	
TOTAL LABOUR CHARGES		:	\$ 4,622.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDB 9330 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - LH	1	\$	3,647.00
2	FRONT DOOR SEAL , OUTER LH	1	\$	275.00
3	BONDING AGENT	1	\$	54.00
4	CLEANING SOLUTION	1	\$	92.00
5	APPLICATOR	1	\$	10.00
6	FRONT DOOR ATTACHMENT PARTS - LH	1	\$	1,179.00
7	FRONT DOOR CATCH - LH	1	\$	131.00
8	FRONT DOOR HANDLE TRIM PLATE	1	\$	166.00
9	FRONT DOOR HANDLE, EXTERIOR	1	\$	53.00
10	FRONT DOOR HANDLE UNDERLAY - LH FRONT / REAR	2	\$	10.00
11	FRONT DOOR MOUNTING BAR - LH	1	\$	206.00
12	FRONT DOOR HANDLE HOUSING - LH	1	\$	12.00
13	FRONT SILL TRIM STRIP - LH	1	\$	149.00
14	STONECHIP	S/N	\$	180.00
15	SUNDRIES		\$	500.00
TOTAL SPARE PARTS		:	\$	6,664.00
TOTAL LABOUR CHARGES		:	\$	4,622.00
GRAND TOTAL		:	\$	11,286.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT