



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24060183/Uqh3
(BUDGET DIRECT INSURANCE)	Date:	21/06/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKV 3674P	Veh. Inspected	SNH 3836C
Policy No.	P10944068R00	Coverage	0
Claim No.	C10030041/HY	Excess	\$0.00
Assign From	CHANG SHI QIAN	Assign Date	21/06/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ S320L (A)	C.C	2996
Engine No.	27682431003940	Year of Reg.	17/06/2019
Chassis No.	WDD2221622A464331	Colour	SILVER
Odometer	41666 KM	Steering	DAMAGED
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/45R19	MICHELIN	5
L/H Front Tyre	245/45R19	MICHELIN	5
R/H Rear Tyre	275/40R19	MICHELIN	5
L/H Rear Tyre	275/40R19	MICHELIN	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/06/2024	Inspection Date	21/06/2024
Survey held at	8 KAKI BUKIT AVE 4 #04-35 PREMIER SINGAPORE 415875-CARSMITH PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days