



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24090468/Uqh3
75 BRAS BASAH ROAD	Date:	14/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 7646G	Veh. Inspected	SLX 7317Y
Policy No.	-	Coverage	0
Claim No.	MT/1296803-001	Excess	\$0.00
Assign From	MARCUS XIAO	Assign Date	25/09/2024

2. Vehicle Details

Make & Model	TOYOTA C-HR HYBRID 1.8S CVT	C.C	1797
Engine No.	2ZR8268246	Year of Reg.	09/04/2018
Chassis No.	ZYX102089834	Colour	GREY
Odometer	293696 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60R17	GOODYEAR	6
L/H Front Tyre	215/60R17	GOODYEAR	6
R/H Rear Tyre	215/60R17	GOODYEAR	6
L/H Rear Tyre	215/60R17	GOODYEAR	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/09/2024	Inspection Date	30/09/2024 (10:43)
Survey held at	WE GARAGE - 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY @ KAKI BUKIT, SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days