


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 25.09.2024

TO : INCOME MOTOR CLAIMS DEPTS
VEHICLE NO : SMA2191J
MODEL : KIA CERATO K3
DATE OF ACCIDENT : 24.09.2024
TIME OF ACCIDENT : 19:15 HOURS

Hui Rong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dented</i>	1	\$ 698.00	\$ 698.00
2	REAR BUMPER REFLECTOR <i>crackd</i>	2	\$ 151.00	\$ 302.00
3	REAR BUMPER SIDE INNER GARNISH <i>new</i>	2	\$ 85.00	\$ 170.00
4	REAR BUMPER CENTER LOWER <i>Dented</i>	1	\$ 286.00	\$ 286.00
5	REAR BUMPER BRACKET <i>new</i>	5	\$ 35.00	\$ 175.00
6	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 27.00	\$ 54.00
7	REAR BUMPER REINFORCEMENT <i>crackd</i>	1	\$ 390.00	\$ 390.00
8	REAR BUMPER REINFORCEMENT BRACKET <i>LH Dented</i>	2	\$ 65.00	\$ 130.00
9	REAR FENDER INNER COWLING <i>new</i>	2	\$ 95.00	\$ 190.00
10	REAR FENDER INNER TRIM <i>new</i>	2	\$ 185.00	\$ 370.00
11	TAIL LAMP <i>LH crackd</i>	2	\$ 798.00	\$ 1,596.00
12	BOOT LID <i>Dented</i>	1	\$ 1,073.00	\$ 1,073.00
13	BOOT LID LOGO	1	\$ 33.00	\$ 33.00
14	BOOT LID EMBLEM 'K3' <i>new</i>	1	\$ 44.00	\$ 44.00
15	BOOT LID EMBLEM 'CERATO' <i>new</i>	1	\$ 43.00	\$ 43.00
16	BOOT LID LAMP <i>new RH cut</i>	2	\$ 710.00	\$ 1,420.00
17	BOOT LID STOPPER <i>2 App</i>	2	\$ 19.00	\$ 38.00
18	BOOT LID HINGE <i>new</i>	2	\$ 66.00	\$ 132.00
19	BOOT LID INSULATOR <i>new</i>	1	\$ 82.00	\$ 82.00
20	BOOT LID WEATHER STRIP <i>cut</i>	1	\$ 110.00	\$ 110.00
21	BOOT LID LOCK <i>Dented</i>	1	\$ 117.00	\$ 117.00
22	BOOT LID LOWER LOCK <i>new</i>	1	\$ 26.00	\$ 26.00
23	REVERSE CAMERA <i>new</i>	1	\$ 895.00	\$ 895.00
24	REAR END PANEL <i>Dented</i>	1	\$ 375.00	\$ 375.00

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMA2191J**
 MODEL : **KIA CERATO K3**
 DATE OF ACCIDENT : 24.09.2024
 TIME OF ACCIDENT : 19:15 HOURS

25	REAR END PANEL TOP GARNISH <i>Del'd</i>	1	\$ 84.00	\$ 84.00	<i>c</i>
26	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 210.00	\$ 210.00	<i>+</i>
27	REAR TOOLS SPONGE <i>new</i>	1	\$ 199.00	\$ 199.00	<i>+</i>
28	REAR CHASSIS MEMBER LH <i>new</i>	1	\$ 983.00	\$ 983.00	<i>+</i>

5128
7615.20

TOTAL PRICE \$ 10,225.00
 LESS 10% \$ 1,022.50
SUB TOTAL PRICE \$ 9,202.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
2	REAR BUMPER DIFFUSER (SPECAIL TYPE) <i>curled</i>	1	\$ 1,500.00	\$ 1,500.00	<i>700</i>
3	BOOT LID INSULATOR CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
4	BOOT LID EMBLEM 'C&C' <i>new</i>	1	\$ 120.00	\$ 120.00	<i>45</i>
5	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
6	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
7	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
8	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
9	TRIALANGLE BREAKDOWN SIGN <i>Del'd</i>	1	\$ 180.00	\$ 180.00	<i>100</i>

935

TOTAL \$ 2,230.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, WELDING GRAZING, CUT, JOIN, STRAIGHTEN ALL AFFECTED PARTS	\$ 1,800.00	<i>700</i>
2	TO PUTTY, POLISH, SPRAY PAINT, WAX ALL AFFECTED PANELS	\$ 1,600.00	<i>700</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING CHECK	\$ 180.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	<i>60</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMA2191J**
MODEL : **KIA CERATO K3**
DATE OF ACCIDENT : 24.09.2024
TIME OF ACCIDENT : 19:15 HOURS

8	TRANSFER BOOTLID MECHANISM	\$ 80.00	60
9	CONDUCT WATER LEAKAGE TEST	\$ 150.00	x
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 4,750.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,432.50
TOTAL LABOUR COST : \$ 4,750.00
TOTAL REPAIR COST : \$ 16,182.50

1710

Adrian Lj
2/8 26/09/24
06 days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

total: 7260.20

2/8: 5.81c ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: