

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowok@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 26.09.2024

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **PD1156S**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 25.9.2024
TIME OF ACCIDENT : 09:55 HOURS

Xiao Chen.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	CENTER PILLAR (OUTER) RH <i>Dented</i>	1	\$ 1,325.60	\$ 1,325.60
2	FRONT WHEEL ARCH RUBBER RH <i>new</i>	1	\$ 92.20	\$ 92.20
3	FRONT WHEEL CAP RH <i>Let</i>	1	\$ 328.60	\$ 328.60
4	FRONT LOWER ARM RH <i>But</i>	1	\$ 690.00	\$ 690.00
5	FRONT UPPER ARM RH <i>But</i>	1	\$ 650.00	\$ 650.00
6	FRONT SHOCK ABSORBER RH <i>But</i>	1	\$ 465.00	\$ 465.00
7	FRONT KNUCKLE ARM RH <i>Dnd</i>	1	\$ 745.00	\$ 745.00
8	FRONT LINKAGE RH <i>new</i>	1	\$ 105.00	\$ 105.00
9	FRONT STEERING RACK & PINION <i>But</i>	1	\$ 1,965.00	\$ 1,965.00
10	SIDE PANEL RH (FRONT) <i>Repair</i>	1	\$ 2,979.00	\$ 2,979.00

180/50
585
558
395
690.

549860 S.N: 180
4123.95

TOTAL PRICE \$ 9,345.40
LESS 25% \$ 2,336.35
SUB TOTAL PRICE \$ 7,009.05

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	CENTER PILLAR OUTER SEALANT RH <i>new</i>	1	\$ 250.00	\$ 250.00
2	REAR SIDE PANEL STICKER 'EXCURSION BUS' RH <i>new</i>	1	\$ 120.00	\$ 120.00
3	SIDE PANEL GLASS SEALANT (FRONT) RH <i>2</i>	1	\$ 80.00	\$ 80.00
4	SIDE PANEL GLASS INNER SEAL (FRONT) RH <i>new</i>	1	\$ 60.00	\$ 60.00
5	SIDE PANEL GLASS SEALANT(CENTER) RH <i>new</i>	1	\$ 80.00	\$ 80.00
6	SIDE PANEL GLASS INNER SEAL (CENTER) RH <i>new</i>	1	\$ 60.00	\$ 60.00

60
40
+

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **PD1156S**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 25.9.2024
 TIME OF ACCIDENT : 09:55 HOURS

7	FRONT WHEEL RIM RH <i>Dentyl</i>	1	\$ 250.00	\$ 250.00 <i>180</i>
8	FRONT WHEEL TYRE RH <i>Men</i>	1	\$ 450.00	\$ 450.00 <i>+</i>
			TOTAL	\$ 1,350.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	<i>500</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	<i>600</i>
3	TUFF COAT	\$ 250.00	<i>30</i>
4	WIRING CHECK	\$ 80.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	<i>+</i>
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	<i>200</i>
7	TO PRESS FRONT WHEEL BEARING	\$ 80.00	<i>+</i>
8	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 350.00	<i>120</i>
9	FOR WHEEL ALIGHMENT	\$ 120.00	<i>80</i>
10	REMOVE AND REFIX REAR SIDE PANEL GLASS RH X2	\$ 280.00	<i>+</i>
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>+</i>

TOTAL \$4,840.00

ESTIMATE REPORT

KK Auto Consultants hence notify
 the Repairs will be following:
 • To remove damaged parts and spray painting
 • To display damaged part(s) during survey
 • Parts prices are subject to confirmation
 • Third party survey is on the way

TOTAL PARTS COST	\$ 8,359.05
TOTAL LABOUR COST	\$ 4,840.00
TOTAL REPAIR COST	\$ 13,199.05

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY, WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

Acknowledged by Repairer
 Signature:
 Date:

Adrian
2/8 26/09/24
05 hrs

total: 6143.95
4/s: 4.9/k ✓