

ESTIMATED ACCIDENT REPAIR COST



TOWER TRANSIT

Co. / GST Reg No. 201419417K

ACCIDENT TIME REPORTED	14:42 HRS
ACCIDENT DATE	18-Sep-24
BUS CAPTAIN NAME	SARIZAL BIN KARADI
THIRD PARTY CLAIM AGAINST	China Taiping Insurance

BUS REGISTRATION NUMBER	SBS3344P
BUS TYPE (SD/DD)	DD
BUS ROUTE NO.	
BUS ADVERT (Y/N)	Y

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	NSF VIEW MIRROR	1	\$ 2,025.96
2	REFLECTOR STICKER	1	\$ 88.00
		9% GST	\$ 190.26
		PARTS TOTAL COST	\$ 2,304.21

SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)			TOTAL COST
TO DISMANTLE & REPLACE :- <ul style="list-style-type: none">DISMANTLE AND REPLACE ITEM NO :1-2			\$ 1,300.00
TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS :- <ul style="list-style-type: none">FRONT LOWER DOME			\$ 650.00
SPRAY PAINTING :- <ul style="list-style-type: none">FRONT LOWER DOME			\$ 640.00
SPRAY PAINTING \$640 PER PANEL LABOUR CHARGES \$650 PER DAY		9% GST	\$ 233.10
		LABOUR TOTAL COST	\$ 2,823.10

SECTION 3 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

		DATE IN	18/Sep/2024
		DATE & TIME SURVEY	
		DATE OUT	
		TOTAL NUMBER OF DAYS	5
BUS TYPE (SD / DD)	DD		
LOSS OF USE COST		\$2,000.00	

SUMMARY	
SECTION NO.	COST
1	\$ 2,304.21
2	\$ 2,823.10
3	\$ 2,000.00
TOTAL	\$ 7,127.31