

ESTIMATED ACCIDENT REPAIR COST



TOWER TRANSIT

Co. / GST Reg No. 201419417K

ACCIDENT TIME REPORTED	14:42 HRS
ACCIDENT DATE	18-Sep-24
BUS CAPTAIN NAME	SARIZAL BIN KARADI
THIRD PARTY CLAIM AGAINST	China Taiping Insurance

BUS REGISTRATION NUMBER	SBS3344P
BUS TYPE (SD/DD)	DD
BUS ROUTE NO.	
BUS ADVERT (Y/N)	Y

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	NSF VIEW MIRROR <i>sch</i>	1	\$ 2,025.96
2	REFLECTOR STICKER <i>sch</i>	1	\$ 88.00
		9% GST	\$ 190.26
		PARTS TOTAL COST	\$ 2,304.21

2113.96

SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE :- • DISMANTLE AND REPLACE ITEM NO :1-2	<i>975</i> { \$ 1,300.00
TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS :- • FRONT LOWER DOME	\$ 650.00
SPRAY PAINTING :- • FRONT LOWER DOME	<i>1615</i> \$ 640.00
SPRAY PAINTING \$640 PER PANEL LABOUR CHARGES \$650 PER DAY	9% GST \$ 233.10 LABOUR TOTAL COST \$ 2,823.10

SECTION 3 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

DATE IN	18/Sep/2024
DATE & TIME SURVEY	
DATE OUT	
TOTAL NUMBER OF DAYS	5
BUS TYPE (SD / DD)	DD
LOSS OF USE COST	\$2,000.00

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2113.96
1615.100
3728.96

Rasul
Hp 97000068
3 decup
P/P
Reg after repair

SUMMARY	
SECTION NO.	COST
1	\$ 2,304.21
2	\$ 2,823.10
3	\$ 2,000.00
TOTAL	\$ 7,127.31