



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 2/7/2024
VEHICLE : SDQ3446R
MAKE/MODEL : TOYOTA / WISH
CHASSIS NO : ZGE20-0008423
MILLAGE :
TYRE SIZE : 205/60/R16
DOA : 18/06/2024

Not Authorized
L1 Pump @ 5300/h
Resurvey After Paint
6 days

LIST ITEM

01 PC TAIL GATE 1825
02 PC TAIL GATE ABSORBER @ \$263.88
01 PC TAIL GATE TRIMBOARD
01 PC TAIL GATE OUTER GANISH
01 PC TAIL GATE OUTER HANDLE
01 PC TAIL GATE EMBLEM (LOGO)
01 PC TAIL GATE INNER LOCK
01 PC TAIL GATE CATCH LOCK
01 PC TAIL GATE INNER HANDLE
01 PC REAR BUMPER 761.20
02 PC REAR BUMPER SIDE RETAINER @ \$126.89
02 PC REAR BUMPER REFLECTOR @ \$75.58
01 PC REAR END PANEL 721.30
01 PC REAR END PANEL TOP GANISH
01 PC REAR WEATHERSTRIP
01 PC REAR LH TAIL LAMP 580.50
01 PC REAR LH TAIL LAMP LOWER BRACKET
01 PC REAR LH TAIL GATE LAMP 401.50
01 PC REAR LH FENDER 1013.50
01 PC REAR LH FENDER INNER SHEILD 175.80
01 PC FUEL FILLER LID
01 PC FUEL FILLER SHEILD

By \$ 2,179.68 ✓
Pn \$ 527.76 X
\$ Pn 414.69 X
Pn 407.82 X
\$ Pn 114.45 X
\$ Pn 64.05 ✓
\$ Pn 335.85 X
\$ Pn 117.72 X
\$ Pn 147.15 X
By \$ 2,200.23 ✓
n/cmt \$ 253.78 ✓
n/cmt \$ 151.16 ✓
By \$ 856.70 ✓
Pn \$ 325.59 X
\$ Pn 325.59 X
Pn \$ 904.77 ✓
CMT \$ 132.10 ✓
Pn \$ 594.69 ✓
Pn \$ 1,713.57 ✓
CMT 201.36 ✓
\$ Pn 128.85 X
\$ Pn 66.48 X
\$ 12,164.04

Special Nett

02 PC PARKING SENSOR @ \$220
10 PC REAR TRIM BOARD CLIP @ \$8
01 PC REAR WINDSCREEN/GLASS SEALANT
06 PC BUMPER CLIP @ \$8

By \$ 440.00 X
Pn 80.00 ✓
Pn 200.00 ✓
Pn 48.00 ✓
\$ 768.00

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECTED AREA
3. TO SUPPLY LABOUR TO ALIGN REAR FENDER
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS
5. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL
6. TO SUPPLY DIAGNOSTIC & REPROGRAMMING
7. TO SUPPLY LABOUR TO REMOVE & REFIT REAR WINDSCREEN AND QUATER GLASS

\$ 1,200.00 1000
\$ 900.00 800
\$ 600.00 X
\$ 300.00 200
\$ 200.00 600
\$ 300.00 X
\$ 400.00 1800
\$ 3,900.00

TOTAL PARTS
TOTAL SPECIAL NETT
TOTAL LABOUR
TOTAL COST OF REPAIR

\$ 12,164.04
\$ 768.00
\$ 3,900.00
\$ 16,832.04

Acknowledged by Repairer

Signature:

Date:

KK Auto Consultants hence notify
To resurvey before/after spray painting
To display damaged part(s) during resurvey
Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company