

REF:

ASSIGNMENT

From: _____ Date: _____

Estimate No: _____

OD / TP RES / CD RES / EVA / INV / MV

To In: _____ Vehicle No: _____

at Work: _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMW86241Yr Regn: 2020, DecType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Yaris CrossC.D. 1490Colour: Red

A/C: Insured / Std / NI / NA

Sp. Reading: 107532

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ITDKBAB3X0L002689Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Triangle

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 27/09/24Survey held at B. FrostDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 8MRT

COE Expiry :

Estimate given during : Yes (✓)
1st Survey : No ()

MV :

PV :

Nett :

Date/Time, File Pass to?



Preli. Report

Days Of Repair: _____

1)



Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Addl Fee: ☐ : Site Insp (\$ _____)

Interview (\$ _____)



Tech. Inve (\$ _____)



Other (\$ _____)

Survey Fee: _____

Transportation: _____

Photos

Others

Report Format: _____

E. Region 24 Hrs / 1 P. / 1 C.

https://singapore.marimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=dsp_clmheader&caseid=1462829&extid=463461&CEID=373...

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: SMW8620H

Make & Model: Toyota Yaris Cross

Chassis number: JTDKBAB3X0L002689

No.	Description of spare parts	Qty	Amount S\$	
1	Tailgate <i>Dented</i>	1	\$ 2,175.40	✓
2	Tailgate windscreen glass rubber moulding <i>new</i>	1	\$ 38.90	✓
3	Tailgate "Yaris Cross" emblem <i>new</i>	1	\$ 63.40	✓
4	Tailgate centre emblem <i>new</i>	1	\$ 56.70	+
5	Tailgate "Hybrid" emblem <i>new</i>	1	\$ 83.40	✓
6	Tailgate centre lamp <i>new</i>	1	\$ 609.80	+
7	Tailgate lock <i>Dented</i>	1	\$ 647.10	✓
8	Tailgate lock catch <i>new</i>	1	\$ 66.70	+
9	Tailgate inner trim board <i>Cracked</i>	1	\$ 743.20	✓
10	Tailgate inner trim board clips <i>in</i>	1set	\$ 70.00	30
11	Tailgate RH lamp <i>new</i>	1	\$ 514.80	+
12	Tailgate LH lamp <i>new</i>	1	\$ 514.80	+
13	Tailgate wiper motor <i>new</i>	1	\$ 677.30	+
14	Rear bumper (upper) <i>Dented</i>	1	\$ 444.00	✓
15	Rear bumper (lower) <i>Dented</i>	1	\$ 766.70	✓
16	Rear bumper RH reflector <i>new</i>	1	\$ 83.40	+
17	Rear bumper LH reflector <i>new</i>	1	\$ 83.40	+
18	Rear bumper RH side reverse sensor <i>new</i>	1	\$ 503.90	+
19	Rear bumper RH side reverse sensor lock clips <i>new</i>	1	\$ 55.20	+
20	Rear bumper RH reverse sensor <i>Dented</i>	1	\$ 503.90	+
21	Rear bumper RH reverse sensor lock clips <i>new</i>	1	\$ 55.20	+
22	Rear bumper LH reverse sensor <i>Dented</i>	1	\$ 503.90	+
23	Rear bumper LH reverse sensor lock clips <i>new</i>	1	\$ 55.20	+
24	Rear bumper LH side reverse sensor <i>new</i>	1	\$ 503.90	+
25	Rear bumper LH side reverse sensor lock clips <i>new</i>	1	\$ 55.20	+
26	Rear bumper RH side retainer <i>new</i>	1	\$ 153.50	+
27	Rear bumper LH side retainer <i>new</i>	1	\$ 153.50	+
28	End panel <i>Dented</i>	1	\$ 1,058.90	✓
29	End panel inner garnish <i>Dented</i>	1	\$ 440.10	✓
30	End panel inner garnish clips <i>new</i>	1set	\$ 70.00	30
31	RH taillamp assy	1	\$ 679.40	+
32	RH taillamp gasket	1	\$ 88.90	+
33	RH taillamp panel	1	\$ 201.20	+
34	RH taillamp lock clips <i>new</i>	1set	\$ 50.00	+
35	LH taillamp assy	1	\$ 679.40	+
36	LH taillamp gasket	1	\$ 88.90	+
37	LH taillamp panel	1	\$ 201.20	+
38	LH taillamp lock clips	1set	\$ 50.00	+

39	Rear antenna sensor <i>could</i>	1	\$	100.00	✓
40	Rear compartment panel board <i>detached</i>	1	\$	557.80	✓
41	Spare tyre sponge <i>new</i>	1	\$	129.10	+
42	Rear RH fender inner trim board	1	\$	829.80	+
43	Rear RH fender inner trim board clips <i>new</i>	1set	\$	70.00	+
44	Rear LH fender inner trim board <i>new</i>	1	\$	829.80	+
45	Rear LH fender inner trim board clips	1set	\$	70.00	+
46	Exhaust silencer <i>new</i>	1	\$	1,502.30	+
47	Exhaust silencer gasket	1	\$	66.80	+

\$ 17,946.00
 Parts less 25% \$ 4,486.50
 Total: \$ 13,459.50

No.	Special Nett Items	Qty	Amount S\$	
1	Tailgate windscreen glass sealant <i>new</i>	1	\$ 80.00	40
2	Tailgate windscreen glass inner seal	1	\$ 60.00	30
3	Tailgate reverse camera <i>new</i>	1	\$ 680.00	+
4	End panel joint sealant <i>new</i>	1	\$ 80.00	60

Total: \$ 900.00

No.	Labour and painting	Amount S\$	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,800.00	700
2	Spray painting on affected areas and panels	\$ 1,600.00	600
3	Check wiring and lighting system on affected areas	\$ 80.00	30
4	Apply rust coating chemical on affected areas and panels	\$ 100.00	60
5	Remove and replace tailgate windscreen glass to assist repair	\$ 220.00	120
6	Remove and replace tailgate reverse camera to assist repair	\$ 100.00	50
7	Remove and replace tailgate inner mechanism to new tailgate	\$ 120.00	60

8	Remove and replace rear bumper reverse sensors	\$	80.00	50
9	Remove and replace rear inner trims and garnish to assist repair	\$	380.00	60
10	Remove and replace exhaust silencer and gasket to assist repair	\$	180.00	4

Total: \$ 2,860.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 13,459.50

Special Nett: \$ 900.00

Labour: \$ 2,860.00

Total: \$ 17,219.50

Adrian King
1/s 27/09/20
06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: