



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 64708686



MAXUS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
YANG DALEI 1 Fraser Street #26-14 DUO RESIDENCES Singapore 189350 Contact No Mobile: 91173999	Cust No/Name	/YANG DALEI
	Reg No/Reg Date	SNS9876P / 18/07/2024
	Date In/Mileage	/ 0
	Chassis No	LSKG48L18RD049369
	Engine No	A124131A10140162
	Make/Model	MAX/MIFA9 90KWH PREMIUM
	Colour/Trim	MB / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00147	Cash	26/09/2024/ 18:31		1210/ Lim Teng Keat	50926		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							2560.00
REPAIR REAR BUMPER, REAR FENDER RH, REAR DOOR RH							
FRT DOOR RH							
E PNT98000							2750.00
SPRAY PAINT FOR REAR BUMPER, REAR FENDER RH, REAR DOOR RH							
FRT DOOR RH							
A WHEELALIGNMENT120L							250.00
To Conduct Computerize Full Wheel Alignment							
M SUNDRY							120.00
TRNASFER REAR RIM							
M SUNDRY							400.00
RIM COVER							
NC00484330							
M SUNDRY							80.00
SUNDRY							
M PANEL-FRT S/D UND TR				1.00	108.00	00.00	108.00
M PANEL-RR S/D UND TR				1.00	155.00	00.00	155.00
M PLATE-W/BASE SK MBR				1.00	12.00	00.00	12.00

Estimate

Confirm & accepted by

9% GST on	Nett 6435.00	6,435.00 579.15
Total Payable		7,014.15

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.