



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

INV No. : SAC2400828

INV Date : 04-10-2024

Reference CS3/SMR24090496/Rnp3e2

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. SLH 8653D
Insured Veh. SHB 928T
Claim No. TAX/09/24/2086
Policy No.
Accident Date 25/09/2024
Inspection Date 27/09/2024

Description	Amount
Pre-Repair Survey	128.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS STRIDES PREMIER AUTOMOTIVE SERVICES PL. Ref: CS3/SMR24090496/Rnp3e2
60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE Date: 04/10/2024
757705 Code: SMR

1. Policy Particulars :- PRE-REPAIR SURVEY

Insured Veh.	SHB 928T	Veh. Inspected	SLH 8653D
Policy No.	-	Coverage	0
Claim No.	TAX/09/24/2086	Excess	\$0.00
Assign From	HUA YEN	Assign Date	27/09/2024

2. Vehicle Details

Make & Model	HONDA SHUTTLE 1.5 HYBRID	C.C	1496
Engine No.	LEB4263450	Year of Reg.	22/11/2016
Chassis No.	GP71043553	Colour	BLACK
Odometer	205827 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/55 R15	ZEXTOUR	6
L/H Front Tyre	195/55 R15	ZEXTOUR	6
R/H Rear Tyre	195/55 R15	ZEXTOUR	6
L/H Rear Tyre	195/55 R15	ZEXTOUR	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

5. General Information

Accident Date	25/09/2024	Inspection Date	27/09/2024 (11:24)
Survey held at	TM MOTOR PTE LTD - 48 TOH GUAN ROAD EAST, TOH GUAN ENTERPRISE HUB #03-116 SINGAPORE 608586		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SLH 8653D



PHOTOGRAPHS FOR VEHICLE NO. : SLH 8653D



PHOTOGRAPHS FOR VEHICLE NO. : SLH 8653D



PHOTOGRAPHS FOR VEHICLE NO. : SLH 8653D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. : SLH 8653D



PHOTOGRAPHS FOR VEHICLE NO. : SLH 8653D



PHOTOGRAPHS FOR VEHICLE NO. : SLH 8653D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 7)

PHOTOGRAPHS FOR VEHICLE NO. : SLH 8653D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 7)

PHOTOGRAPHS FOR VEHICLE NO. : SLH 8653D



PHOTOGRAPHS FOR VEHICLE NO. : SLH 8653D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 4 of 7)

PHOTOGRAPHS FOR VEHICLE NO. : SLH 8653D



PHOTOGRAPHS FOR VEHICLE NO. : SLH 8653D



PHOTOGRAPHS FOR VEHICLE NO. : SLH 8653D



PHOTOGRAPHS FOR VEHICLE NO. : SLH 8653D



PHOTOGRAPHS FOR VEHICLE NO. : SLH 8653D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 3)

PHOTOGRAPHS FOR VEHICLE NO. : SLH 8653D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 3 of 3)

PHOTOGRAPHS FOR VEHICLE NO. : SLH 8653D

