



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920

* zoomautowerks@gmail.com

No f Andrew
Mr
Maras
27/9/24
2/3 \$2500
4 days

REG NO.: SNA 1522 H
MAKE/MODEL: HONDA CRV

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

KK Auto Consultants hence notify
the Repairer of the following: 30 September 2024

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AMT(\$)

QTY	DESCRIPTION		AMT(\$)
	<u>LIST ITEMS</u>		
1	Front bonnet	\$ 2	716.90 X
1	Front headlamp. n/s	1325.80 \$ one	2,116.40 ✓
1	Front grille outer garnish	\$ one	357.30 ✓
1	Front grille lower	\$ one	224.60 ✓
1	Front grille logo	\$ 17	82.20 X
1	Front grille chrome moulding	\$ 12	239.60 X
1	Front top bumper	\$ 222	467.80 ✓
1	Front lower bumper	\$ n/s	460.60 X
1	Front bumper top beam	\$ 2	102.00 X
2	Front bumper fog lamps	\$ 11 one	495.20 X
2	Front bumper fog lamp rims	\$ 11	228.40 X
1	Front bumper reinforcement	\$ 222	280.80 ✓
2	Front bumper side retainers	\$ 17	53.80 X
1	Front number plate garnish	\$ set on	86.90 ✓
2	Front fender wheel arch garnishes	\$ 17	650.00 X
		\$	6,562.50
		Less 20% \$	1,312.50
		\$	5,250.00

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	\$ 111	50.00 40 S/N
1	Front bumper PDC sensor (1 set)	\$ 17	280.00 X
1	Front number plate with holder	\$ 50	50.00 40 S/N
		\$	380.00

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00 20
2	To remove and refit front sensor.	\$ 12	120.00 X
3	Panel beating.	\$	1,200.00 380
4	To re-spray painting on the affected areas.	\$	1,100.00 550
		\$	2,500.00

GRAND TOTAL :

\$ 8,130.00
2,2742.90
200
219432
80
950