

ESTIMATE

24/9/2024

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00
Springleaf Tower
Singapore 079909

Vehicle No: SLB923J
Vehicle Model: T/AXIO
Est No: CBMQ24090226
Claims ref:
Accident Date: 19/09/24
In Charge: KEONG
Remarks:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	HEADLAMP RH <i>cm</i>	1	PC \$ 1,476.50	\$ 1,476.50
2	HEADLAMP BRACKET RH <i>?</i> nn	1	PC \$ 27.50	\$ 27.50
3	FRONT BUMPER <i>sur</i>	1	PC \$ 1,127.60	\$ 1,127.60
4	FRONT BUMPER SIDE BRACKET RH <i>?</i> nn	1	PC \$ 86.30	\$ 86.30
5	FRONT BUMPER SIDE COVER RH <i>X</i> nn	1	PC \$ 87.70	\$ 87.70
6	FRONT BUMPER FOG LIGHT RH <i>X</i> nn	1	PC \$ 295.40	\$ 295.40
7	FRONT BUMPER CLIPS <i>cm</i>	10	PC \$ 5.10	\$ 51.00
8	FRONT GRILLE <i>cm</i>	1	PC \$ 396.50	\$ 396.50
9	FRONT FENDER RH - REPAIR	1	PC	\$ -
10	FRONT SUPPORT PANEL - REPAIR	1	PC	\$ -
LIST TOTAL S\$				\$ 3,548.50
25% DISCOUNT S\$				\$ (887.13)
				<u>\$ 2,661.38</u>

LABOUR CHARGE:			
1	TO REPAIR FRONT FENDER RH, SUPPORT PANEL, TO REMOVE & REFIX DAMAGED PARTS, TO STRAIGHTEN & REALIGN AFFECTED AREAS	\$ 560.00	<i>450</i>
2	TO SPRAY FRONT FENDER RH, SUPPORT PANEL, FRONT BUMPER & AFFECTED AREAS	\$ 680.00	<i>500</i>
3	TO CHECK WIRING & FOCUS HEADLIGHT	\$ 60.00	<i>30</i>
TOTAL LABOUR COST S\$		<u>\$ 1,300.00</u>	

AMOUNT S\$ \$ 3,961.38
GST @ 9% \$ 356.52
AMOUNT DUE S\$ \$ 4,317.90

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

ESTIMATE

24/9/2024

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00
Springleaf Tower
Singapore 079909

Vehicle No: SLB923J
Vehicle Model: T/AXIO
Est No:CBMQ24090226
Claims ref:
Accident Date: 19/09/24
In Charge: KEONG
Remarks:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No	Description	Qty	U. Price	Amounts S\$
----	-------------	-----	----------	-------------

- LKK Auto Consultants hence notify
the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rame
Hp 90010068
4 days
L/S
01/10/24
Reg after
refer