

(08/11/13) Wel

ASS. REC. BY:

REF: CS/SMB 24090501/Rq3

417K

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMB 350SBat Workshop m/s TOWEL TRANSITof BULIM DRInsured: SMR

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMB 350SB Yr Regn: 2014 / AUG

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: ALEXANDER DENNIS C.C. 8849Colour: GREEN AC: Insured / Std / NI / NASp. Reading: 588991 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SFD 76CLRSEMTL3370

Condition: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nib / S/Rim / STD A/Rim or _____

Tyre Size: F: 305/70R22.5R: 2 - 510

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or PIRELLA

Front

Rear

R/Bal. 8 mm R/Bal. 8/8 mmL/Bal. 8 mm L/Bal. 8/8 mmD.O.A. 22/09/14 D.O.I. 30/09/14Survey held at BULIM DR

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

1)

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)) S + RS _____☐ : Interview (\$ _____)) Photos☐ : Tech. Invs (\$ _____)) Others☐ : Weekend (\$ _____))

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL

ESTIMATED ACCIDENT REPAIR COST



TOWER TRANSIT

Co. / GST Reg No. 201419417K

ACCIDENT TIME REPORTED	13:00 HRS
ACCIDENT DATE	22-Sep-24
BUS CAPTAIN NAME	CHAN BOON CHEN
THIRD PARTY CLAIM AGAINST	SMRT

BUS REGISTRATION NUMBER	SMB3505B
BUS TYPE (SD/DD)	DD
BUS ROUTE NO.	
BUS ADVERT (Y/N)	N

SECTION 1 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS :- • OSR DOME	325 \$ 650.00
SPRAY PAINTING :- • OSR DOME	\$ 640.00
SPRAY PAINTING \$640 PER PANEL	9% GST \$ 116.10
LABOUR CHARGES \$650 PER DAY	LABOUR TOTAL COST \$ 1,406.10

SECTION 2 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

	DATE IN	22/Sep/2024
	DATE & TIME SURVEY	
	DATE OUT	
	TOTAL NUMBER OF DAYS	2
BUS TYPE (SD / DD)	DD	
LOSS OF USE COST		\$800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SUMMARY

SECTION NO.	COST
1	\$ 1,406.10
2	\$ 800.00
TOTAL	\$ 2,206.10

Ram
Ap 90010068
2 days
30/09/24
Reg after repair