



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBH 4787X

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE	BENT	\$20.00	\$20.00
1	FRONT FENDER WHEEL GUARD	CUT	\$220.00	\$220.00
1	FRONT FORK ASSY	BENT	\$1,700.00	\$1,700.00
1	FRONT FORK BRACKET	BENT	\$380.00	\$380.00
1	FRONT FORK OIL SEAL	NECESSARY	\$50.00	\$50.00
1	FRONT HEADLAMP RIM	BENT	\$225.00	\$225.00
1	FRONT HEADLAMP	BROKEN	\$565.00	\$565.00
1	FRONT HEADLAMP BRACKET	BENT	\$85.00	\$85.00
1	FRONT HEADLAMP FAIRING	BROKEN	\$195.00	\$195.00
1	FRONT WINDSHIELD & BRACKET	BROKEN	\$350.00	\$350.00
1	FRONT WING MIRROR (RH)	MISSING	\$120.00	\$120.00
1	METER ASSY & BRACKET	MISSING	\$1,550.00	\$1,550.00
1	IGNITION SWITCH	BROKEN	\$250.00	\$250.00
1	STEERING CONE	NECESSARY	\$150.00	\$150.00
1	HANDLE BAR	BENT	\$185.00	\$185.00
1	FUEL TANK	DENTED	\$900.00	\$900.00
1	BRAKE RESERVOIR	BROKEN	\$200.00	\$200.00
1	ENGINE CRASH BAR (LH)	BENT	\$400.00	\$400.00
1	SIDE BOX (LH)	BROKEN	\$280.00	\$280.00
1	HELMET	CUT	\$300.00	\$300.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$812.50)
			\$8,125.00	\$7,312.50

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR		\$400.00	\$400.00
	PAINTING		\$300.00	\$300.00
	ELECTRICAL		\$30.00	\$30.00
			\$730.00	\$730.00
GRAND TOTAL			\$8,855.00	\$8,042.50



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$6,450.00
Report Ref No: CS3/SPF24090505/Eqp3m4			

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$6,500

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.