

TO : CHINA TAIPING
 VEHICLE NO : SLT 4078C
 MODEL : KIA CARENS
 CHASSIS : KNAHU815VJ7192774
 DATE OF ACCIDENT : 24.09.2024
 DATE OF REG : 27.10.2017

29	REAR FENDER RH (INNER) <i>Revis</i>	1	\$ 1,385.30	\$ 1,385.30	+
30	REAR FENDER AIRDUCT RH <i>aud</i>	1	\$ 75.30	\$ 75.30	✓
31	REAR QUARTER GLASS WITH MOLDING RH <i>in</i>	1	\$ 358.20	\$ 358.20	65
32	REAR FENDER INNER COWLING RH <i>to</i>	1	\$ 138.90	\$ 138.90	✓
33	REAR FENDER INNER COWLING COVER RH <i>to</i>	1	\$ 65.30	\$ 65.30	+
34	REAR FENDER INNER TRIM TOP RH <i>new</i>	1	\$ 356.30	\$ 356.30	+
35	REAR FENDER INNER TRIM BOTTOM RH <i>del</i>	1	\$ 523.60	\$ 523.60	✓
36	REAR END PANEL <i>Revis</i>	1	\$ 594.00	\$ 594.00	+
37	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 136.80	\$ 136.80	+
38	REAR STORAGE BOX <i>new</i>	1	\$ 386.00	\$ 386.00	+
39	REAR WHEEL HOUSE PANEL RH <i>Revis</i>	1	\$ 846.00	\$ 846.00	+
40	REAR DOOR RH	1	\$ 1,432.50	\$ 1,432.50	+
41	REAR EXHAUST BOX	1	\$ 740.00	\$ 740.00	+
42	REAR EXHAUST INSULATOR	1	\$ 142.00	\$ 142.00	+
43	REAR EXHAUST GASKET (SET)	1	\$ 60.00	\$ 60.00	+
44	REAR EXHAUST MOUNTING	6	\$ 29.00	\$ 174.00	+

6909.16 TOTAL PRICE \$ 15,617.86
 LESS 10% \$ 1,561.79
 6218.24 SUB TOTAL PRICE \$ 14,056.07

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER (UPPER) CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	✓
2	REAR BUMPER (LOWER) CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	✓
3	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
4	QUARTER GLASS SEALANT SET <i>new</i>	1	\$ 80.00	\$ 80.00	30
5	TAILGATE EMBLEM 'CYCLE & CARRIAGE' <i>new</i>	1	\$ 80.00	\$ 80.00	40
6	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	40
7	TAILGATE WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	30
8	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	+
9	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	30
10	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	30
11	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 100.00	\$ 100.00	+
12	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	+

TOTAL \$770.00

260

TO : CHINA TAIPING
 VEHICLE NO : SLT 4078C
 MODEL : KIA CARENS
 CHASSIS : KNAHU815VJ7192774
 DATE OF ACCIDENT : 24.09.2024
 DATE OF REG : 27.10.2017

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,200.00	1400
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	900
3	TUFF COAT	\$ 350.00	80
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 300.00	80
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00	50
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 100.00	50
8	TRANSFER TAILGATE MECHANISM	\$ 80.00	80
9	CONDUCT WATER LEAKAGE TEST	\$ 250.00	x
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 120.00	x
12	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
	REMOVE AND REFIX REAR FENDER QUARTER GLASS	\$ 80.00	50
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	x

TOTAL \$6,050.00

TOTAL PARTS COST : \$14,826.07
 TOTAL LABOUR COST : \$6,050.00
 TOTAL REPAIR COST : \$20,876.07

Admin by
 4/25/09/24

08 Days

total 8888.24
 h/s: 7.2K

7.2K

2510