

ASS. REC. BY:

REF: C721Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s JDof 194N

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4-5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMS 25681 Yr Regn: 02, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Ponto C.C. 1496Colour: M. P. White AC: Insured / Std / Nil / NASp. Reading: 277937 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: NHP 70 780048Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: TeraxR: Anaite 185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front 8 mmR/Bal. 8 mmL/Bal. 8 mmD.O.A. 20/6/24 D.O.I. 21/6/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

S - RS - SI

Fees

Others

Report Format:

Lump Sum / I.B.I.: (\$ _____)

TOTAL



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 03-76 SYNERGY @ KB S417800

DATE 20/06/2024
VEHICLE SMS2568L
MAKE/MODEL TOYOTA / SIENTA
CHASSIS NO NHP170-7180044
MILLAGE 277150KM
TYRE SIZE
DOA 20/06/2024

Not Authorised
L1 Sup &
Recovery After Paint
4-5 days

LIST ITEM

01 PC	TAIL GATE	Rs	2,070.40	✓
02 PC	TAIL GATE HINGES @ \$235.40	Rs	470.80	X
02 PC	TAIL GATE ABSORBER @ \$378.50	Rs	757.00	X
01 PC	TAIL GATE TRIMBOARD	sm	590.30	X
01 PC	TAIL GATE OUTER MOULDING	s	365.90	?
01 PC	TAIL GATE OUTER HANDLE	sm	245.20	X
01 PC	TAIL GATE EMBLEM (HYBRID)	ms	184.90	✓
01 PC	TAIL GATE EMBLEM (LOGO)	sm	230.60	✓
01 PC	TAIL GATE INNER LOCK	s	591.90	✓
01 PC	TAIL GATE CATCH LOCK	s	155.70	X
01 PC	TAIL GATE INNER HANDLE	s	97.85	X
01 PC	REAR BUMPER	Buck	2,128.19	✓
02 PC	REAR BUMPER SIDE RETAINER @ \$185.30	sm	370.60	X
02 PC	REAR BUMPER CORNER PANEL GANISH @ \$246.75	sm	493.50	X
01 PC	REAR BUMPER GARNISH	sm	325.40	✓
01 PC	REAR BUMPER PARKING SENSOR GARNISH	shc	164.90	X
02 PC	REAR BUMPER REFLECTOR @ \$220.90	sm	441.90	X
02 PC	REAR CORNER PANEL @ \$265.30	s	530.60	X
02 PC	REAR CORNER PANEL BRACKET @ \$208.50	s	417.00	X
01 PC	REAR END PANEL	s	1,589.60	?
01 PC	REAR END PANEL TOP GANISH	s	375.60	?
01 PC	REAR WEATHERSTRIP	s	425.15	?
02 PC	REAR TAIL LAMP @ \$785.40	ms	1,570.80	X
02 PC	REAR TAIL GATE LAMP @ \$653.20	ms	1,306.40	X
01 PC	REAR TAIL GATE CAMERA	sm	640.50	X
01 PC	REAR ANTENNA SENSOR	s	389.10	?
			<u>\$ 16,929.79</u>	

25!

Special Net

02 PC	PARKING SENSOR @ \$220	\$	440.00	?
10 PC	REAR TRIM BOARD CLIP @ \$8	na	80.00	X
01 PC	REAR WINDSCREEN SEALANT	\$	100.00	405AL
06 PC	BUMPER CLIP @ \$8	sm	48.00	✓
		<u>\$</u>	<u>668.00</u>	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$	1,200.00	?
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECTED AREA	\$	800.00	600L
3. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$	200.00	20L
4. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	\$	150.00	?
5. TO SUPPLY DIAGNOSTIC & REPROGRAMMING	\$	300.00	?
6. TO SUPPLY LABOUR TO REMOVE & REFIT REAR WINDSCREEN	\$	300.00	120L
	<u>\$</u>	<u>2,950.00</u>	

TOTAL PARTS
TOTAL SPECIAL NETT
TOTAL LABOUR
TOTAL COST OF REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$	16,929.79
\$	668.00
\$	2,950.00
<u>\$</u>	<u>20,547.79</u>