



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 20/06/2024
VEHICLE : SMS2568L
MAKE/MODEL : TOYOTA / SIENTA
CHASSIS NO : NHP170-7180044
MILLAGE : 277150KM
TYRE SIZE :
DOA : 20/06/2024

Not Authorised
L1 Rep \$4300/h
Repair After Rain
5 days

LIST ITEM

01 PC	TAIL GATE	1602.40	By \$	2,070.40	✓
02 PC	TAIL GATE HINGES @ \$235.40		R \$	470.80	X
02 PC	TAIL GATE ABSORBER @ \$378.50		Sn \$	757.00	X
01 PC	TAIL GATE TRIMBOARD		Sn	590.30	X
01 PC	TAIL GATE OUTER MOULDING		Sn	365.90	X
01 PC	TAIL GATE OUTER HANDLE	89.95	By \$	245.20	✓
01 PC	TAIL GATE EMBLEM (HYBRID)		Sn	184.90	✓
01 PC	TAIL GATE EMBLEM (LOGO)	121.60	Sn	230.60	✓
01 PC	TAIL GATE INNER LOCK	480	\$ Nu	591.90	✓
01 PC	TAIL GATE CATCH LOCK		\$ R	155.70	X
01 PC	TAIL GATE INNER HANDLE		\$ R	97.85	X
01 PC	REAR BUMPER	758	By \$	2,128.19	✓
02 PC	REAR BUMPER SIDE RETAINER @ \$185.30		Sn	370.60	X
02 PC	REAR BUMPER CORNER PANEL GANISH @ \$246.75		Sn	493.50	X
01 PC	REAR BUMPER GARNISH		Sn	325.40	✓
01 PC	REAR BUMPER PARKING SENSOR GARNISH		\$ R	164.90	X
02 PC	REAR BUMPER REFLECTOR @ \$220.90		Sn	441.90	X
02 PC	REAR CORNER PANEL @ \$265.30		\$ R	530.60	X
02 PC	REAR CORNER PANEL BRACKET @ \$208.50		\$ R	417.00	X
01 PC	REAR END PANEL	781.60	By \$	1,589.60	✓
01 PC	REAR END PANEL TOP GANISH	261.30	By \$	375.60	✓
01 PC	REAR WEATHERSTRIP		Oil \$	425.15	508.50 212.5750
02 PC	REAR TAIL LAMP @ \$785.40		Sn	1,570.80	X
02 PC	REAR TAIL GATE LAMP @ \$653.20		Sn	1,306.40	X
01 PC	REAR TAIL GATE CAMERA		Sn	640.50	X
01 PC	REAR ANTENNA SENSOR	127 258	GM	389.10	✓
			\$	16,929.79	

Special Nett

02 PC	PARKING SENSOR @ \$220	\$ R	440.00	X
10 PC	REAR TRIM BOARD CLIP @ \$8	na	80.00	X
01 PC	REAR WINDSCREEN SEALANT	\$	100.00	405AL
06 PC	BUMPER CLIP @ \$8	Sn	48.00	✓
			\$	668.00

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$	1,200.00	600L
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECTED AREA	\$	800.00	660L
3. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$	200.00	20L
4. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	\$	150.00	80L
5. TO SUPPLY DIAGNOSTIC & REPROGRAMMING	\$	300.00	X
6. TO SUPPLY LABOUR TO REMOVE & REFIT REAR WINDSCREEN	\$	300.00	120L
		\$	2,950.00

TOTAL PARTS
TOTAL SPECIAL NETT
TOTAL LABOUR
TOTAL COST OF REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: