

Date: 26-9-2024

Vehicle No: SMA5290L

Model: Kia Carens

Chassis: KNAHU815VJ7208157

Reg.Year: 12.6.2018

Third Party Insurer: China Taiping

Third Party Veh No: SMR2815D

Date of Accident: 22/9/2024

Estimator: Loong

Surveyor:

Not Wholesaler
11 Bay & 7300h
Recovery After Paint
5 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER <i>698.60</i>	1		<i>CMA</i> \$750.00
2	REAR BUMPER LOWER	1		<i>CMA</i> \$200.00
3	REAR BUMPER LOWER OUTER MOULDING	1		<i>nu</i> \$190.00
4	REAR BUMPER TOWING COVER	1		<i>nu</i> \$10.00
5	REAR LH FOG LAMP <i>125.90</i>	1		<i>CMA</i> \$180.00
6	REAR REVERSE SENSOR <i>clj rd</i>	2	\$160.00	\$320.00
7	SMART KEY ANTENNA	1		<i>nd</i> \$120.00
8	REAR BUMPER REINFORCEMENT	1		<i>Ry</i> \$350.00
9	REAR LH BUMPER REINFORCEMENT BRACKET	1		<i>Ry</i> \$150.00
10	REAR RH BUMPER REINFORCEMENT BRACKET	1		<i>Ry</i> \$150.00
11	REAR BOOT	1		<i>Ry</i> \$1,300.00
12	REAR BOOT KIA LOGO	1		<i>na</i> \$100.00
13	REAR BOOT CARENS EMBLEM	1		<i>na</i> \$80.00
14	REAR BOOT CRDI EMBLEM	1		<i>na</i> \$40.00
15	REAR BOOT WEATHERSTRIP	1		<i>Red/Dis</i> \$140.00
16	REAR BOOT LOCK	1		<i>Red</i> \$150.00
17	REAR BOOT CENTER CHROME MOULDING	1		<i>pu</i> \$180.00
18	BOOT REFLECTOR LAMP LH	1		<i>pu</i> \$280.00
19	BOOT REFLECTOR LAMP RH	1		<i>pu</i> \$280.00
20	TAILLAMP RH	1		<i>pu</i> \$320.00
21	REAR BOOT INNER TRIM BOARD	1		<i>myent</i> \$280.00
22	REAR END PANEL	1		<i>R</i> \$800.00
23	REAR END PANEL TRIM BOARD	1		<i>my dis</i> \$90.00
24	FRONT BUMPER	1		<i>Bu</i> \$650.00
25	FRONT BUMPER KIA LOGO	1		<i>na</i> \$100.00
26	RADIATOR GRILLE	1		<i>myent</i> \$450.00
27	FRONT BUMPER ENERGY ABSORBER	1		<i>CMA</i> \$90.00
28	FRONT BUMPER REINFORCEMENT	1		<i>Bu</i> \$360.00
29	FRONT BUMPER SKID PLATE	1		<i>pu</i> \$200.00
30	FRONT LH BUMPER FOG LAMP COVER	1		<i>pu</i> \$130.00
31	FRONT RH BUMPER RETAINER	1		<i>pu</i> \$20.00
32	FRONT RH BUMPER SIDE SUPPORT BRACKET	1		<i>CMA</i> \$30.00
33	FRONT RH HEADLAMP <i>1692.50</i>	1		<i>myent</i> \$1,800.00
34	FRONT RADIATOR SUPPORT PANEL	1		<i>pu</i> \$750.00
35	FRONT LH FENDER PANEL	1		REPAIR
36	FRONT RH FENDER PANEL	1		REPAIR
37	FRONT BONNET	1		REPAIR

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 26-9-2024
 Vehicle No: SMA5290L
 Model: Kia Carens
 Chassis: KNAHU815VJ7208157
 Reg.Year: 12.6.2018

Third Party Insurer: China Taiping
 Third Party Veh No: SMR2815D
 Date of Accident: 22/9/2024
 Estimator: Loong
 Surveyor:

38	REAR BOOT OUTER GARNISH	1		REPAIR
			SUB TOTAL	\$11,040.00
			LESS 10%	-\$1,104.00
			PARTS TOTAL	\$9,936.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BUMPER CLIPS	1		nn \$50.00	✓
2	FRONT FENDER LINER CLIPS	1		nn \$50.00	X
3	RADIATOR COOLANT	1		nn \$120.00	X
4	REAR BUMPER CLIPS	1		nn \$50.00	✓
5	REAR BUMPER PROTECTOR	1		nn \$150.00	30sn
6	REAR BUMPER LOWER CLIPS	1		nn \$50.00	✓
7	REAR BOOT INNER TRIM BOARD CLIPS	1		nn \$50.00	X
8	REAR WINDSCREEN SEALANT	1		nn \$120.00	40sn
9	REAR WINDSCREEN PRIMER	1		nn \$100.00	30sn
10	REAR WINDSCREEN MOULDING	1		nn \$150.00	X
11	REAR END PANEL SEALANT	1		nn \$100.00	X
12	REAR BOOT OUTER GARNISH CLIPS	1		nn \$50.00	X
13	TAILLAMP GUIDE CLIPS	1		nn \$50.00	X
14	REAR END PANEL TRIM BOARD CLIPS	1		nn \$50.00	X
15	FRONT LICENCE PLATE NUMBER WITH FRAME	1		nn \$55.00	45sn
16	REAR LICENCE PLATE NUMBER WITH FRAME	1		nn \$55.00	X
			S/N TOTAL	\$1,250.00	

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT & REAR ACCIDENT AREAS & ETC.

\$1,500.00 700

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOT, REAR BUMPER, REAR END PANEL, FRONT BUMPER, FRONT LH & RH FENDER, FRONT BONNET, ETC

\$1,800.00 800

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC.

\$150.00 120

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

\$120.00 60

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 Fax: (+65) 6481 1011



Date: 26-9-2024
Vehicle No: SMA5290L
Model: Kia Carens
Chassis: KNAHU815VJ7208157
Reg.Year: 12.6.2018

Third Party Insurer: China Taiping
Third Party Veh No: SMR2815D
Date of Accident: 22/9/2024
Estimator: Loong
Surveyor:

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$100.00	601
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$150.00	301
TO REMOVE AND REFIT A/C CONDENSER, RADIATOR AND OTHER NEC ITEMS TO ENABLE BODYWORK REPAIR	\$220.00	nn X
TO VACUUM AND TOPUP A/C GAS	\$150.00	nn X
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$100.00	401
TO READJUST AND REALIGN HEADLAMP AIM	\$100.00	nn X
TO REMOVE AND REFIT REAR LUGGAGE COMPARTMENT INNER TRIMMINGS, LININGS, COVER, GARNISH AND OTHER NEC ITEMS TO ENABLE BODYWORK REPAIR	\$300.00	501

LABOUR TOTAL \$4,690.00

TOTAL \$15,876.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9819 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

