

Date: 26-9-2024
Vehicle No: SMA5290L
Model: Kia Carens
Chassis: KNAHU815VJ7208157
Reg.Year: 12.6.2018

Not Wholesaler
6/1 Day &
Repairing After Paint
5-6 days

Third Party Insurer: China Taiping
Third Party Veh No: SMR2815D
Date of Accident: 22/9/2024
Estimator: Loong
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		<i>CMA</i> \$750.00
2	REAR BUMPER LOWER	1		<i>CMA</i> \$200.00
3	REAR BUMPER LOWER OUTER MOULDING	1		<i>RM</i> \$190.00
4	REAR BUMPER TOWING COVER	1		<i>RM</i> \$10.00
5	REAR LH FOG LAMP	1		\$180.00
6	REAR REVERSE SENSOR	2	\$160.00	\$320.00
7	SMART KEY ANTENNA	1		\$120.00
8	REAR BUMPER REINFORCEMENT	1		\$350.00
9	REAR LH BUMPER REINFORCEMENT BRACKET	1		\$150.00
10	REAR RH BUMPER REINFORCEMENT BRACKET	1		\$150.00
11	REAR BOOT	1		<i>RM</i> \$1,300.00
12	REAR BOOT KIA LOGO	1		<i>RM</i> \$100.00
13	REAR BOOT CARENS EMBLEM	1		<i>RM</i> \$80.00
14	REAR BOOT CRDI EMBLEM	1		<i>RM</i> \$40.00
15	REAR BOOT WEATHERSTRIP	1		\$140.00
16	REAR BOOT LOCK	1		\$150.00
17	REAR BOOT CENTER CHROME MOULDING	1		<i>RM</i> \$180.00
18	BOOT REFLECTOR LAMP LH	1		<i>RM</i> \$280.00
19	BOOT REFLECTOR LAMP RH	1		<i>RM</i> \$280.00
20	TAILLAMP RH	1		<i>RM</i> \$320.00
21	REAR BOOT INNER TRIM BOARD	1		\$280.00
22	REAR END PANEL	1		\$800.00
23	REAR END PANEL TRIM BOARD	1		\$90.00
24	FRONT BUMPER	1		\$650.00
25	FRONT BUMPER KIA LOGO	1		\$100.00
26	RADIATOR GRILLE	1		\$450.00
27	FRONT BUMPER ENERGY ABSORBER	1		\$90.00
28	FRONT BUMPER REINFORCEMENT	1		\$360.00
29	FRONT BUMPER SKID PLATE	1		<i>RM</i> \$200.00
30	FRONT LH BUMPER FOG LAMP COVER	1		<i>RM</i> \$130.00
31	FRONT RH BUMPER RETAINER	1		<i>RM</i> \$20.00
32	FRONT RH BUMPER SIDE SUPPORT BRACKET	1		\$30.00
33	FRONT RH HEADLAMP	1		\$1,800.00
34	FRONT RADIATOR SUPPORT PANEL	1		<i>RM</i> \$750.00
35	FRONT LH FENDER PANEL	1		REPAIR
36	FRONT RH FENDER PANEL	1		REPAIR
37	FRONT BONNET	1		REPAIR

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Bik 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 26-9-2024
Vehicle No: SMA5290L
Model: Kia Carens
Chassis: KNAHU815VJ7208157
Reg.Year: 12.6.2018

Third Party Insurer: China Taiping
Third Party Veh No: SMR2815D
Date of Accident: 22/9/2024
Estimator: Loong
Surveyor:

38	REAR BOOT OUTER GARNISH	1		REPAIR
SUB TOTAL				\$11,040.00
LESS 10%				-\$1,104.00
PARTS TOTAL				\$9,936.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BUMPER CLIPS	1		na \$50.00	✓
2	FRONT FENDER LINER CLIPS	1		na \$50.00	X
3	RADIATOR COOLANT	1		na \$120.00	X
4	REAR BUMPER CLIPS	1		na \$50.00	✓
5	REAR BUMPER PROTECTOR	1		na \$150.00	30sn
6	REAR BUMPER LOWER CLIPS	1		na \$50.00	✓
7	REAR BOOT INNER TRIM BOARD CLIPS	1		na \$50.00	X
8	REAR WINDSCREEN SEALANT	1		na \$120.00	40sn
9	REAR WINDSCREEN PRIMER	1		na \$100.00	30sn
10	REAR WINDSCREEN MOULDING	1		na \$150.00	X
11	REAR END PANEL SEALANT	1		\$100.00	?
12	REAR BOOT OUTER GARNISH CLIPS	1		\$50.00	?
13	TAILLAMP GUIDE CLIPS	1		na \$50.00	X
14	REAR END PANEL TRIM BOARD CLIPS	1		na \$50.00	X
15	FRONT LICENCE PLATE NUMBER WITH FRAME	1		na \$55.00	45sn
16	REAR LICENCE PLATE NUMBER WITH FRAME	1		na \$55.00	X
S/N TOTAL				\$1,250.00	

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT & REAR ACCIDENT AREAS & ETC. \$1,500.00 ?

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOT, REAR BUMPER, REAR END PANEL, FRONT BUMPER, FRONT LH & RH FENDER, FRONT BONNET, ETC. \$1,800.00 8001

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC. \$150.00 1201

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS. \$120.00 601

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011



Date: 26-9-2024
Vehicle No: SMA5290L
Model: Kia Carens
Chassis: KNAHU815VJ7208157
Reg.Year: 12.6.2018

Third Party Insurer: China Taiping
Third Party Veh No: SMR2815D
Date of Accident: 22/9/2024
Estimator: Loong
Surveyor:

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$100.00	601
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$150.00	7
TO REMOVE AND REFIT A/C CONDENSER, RADIATOR AND OTHER NEC ITEMS TO ENABLE BODYWORK REPAIR	\$220.00	nn X
TO VACUUM AND TOPUP A/C GAS	\$150.00	nn X
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$100.00	401
TO READJUST AND REALIGN HEADLAMP AIM	\$100.00	nn X
TO REMOVE AND REFIT REAR LUGGAGE COMPARTMENT INNER TRIMMINGS, LININGS, COVER, GARNISH AND OTHER NEC ITEMS TO ENABLE BODYWORK REPAIR	\$300.00	7

LABOUR TOTAL \$4,690.00

TOTAL \$15,876.00

