



ESTABLISHED 1984

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC24090511/Aqh3e2

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 24/02/2026

ATTN: RAJESWARY

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBQ 2228J	Veh. Inspected	SLH 2445C
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1295101-002	Excess (\$)	0.00
Assign From	JULIET KOH	Assign Date	27/09/2024

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 116D HB	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WBA1V720405C07327	Colour	BLACK
Odometer	194234 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/09/2024	Inspect Date / Time	30/09/2024 (02:15 PM)
Survey held at	TSL AUTO PRO SELECTION PTE LTD BLK 1 KAKI BUKIT AVENUE 6 #01-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**