

ASSIGNMENT

Front: _____ Date: _____

Estim: _____

OD / TP RES / OD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at W _____ m/s

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDS448U Yr Regn: 2018 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra C.D. 1591

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 33243 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHD841CMJU72670

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 30/09/24

Survey held at JL Perked

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP III</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No (✓)</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>
	<u>7608</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$1

Photos

Others

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Inve (\$)

Report Format: _____

Report Form: _____

Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail: jlperfectautowork@gmail.com



DATE : 30.09.2024

TO	: INDIA INTERNATIONAL MOTOR CLAIMS DEPTS
VEHICLE NO	: SDS448U
MODEL	: HYUNDAI ELANTRA
DATE OF ACCIDENT	: 16.09.2024
TIME OF ACCIDENT	: 16:00 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>torn</i>	1	\$ 798.40	\$ 798.40
2	FRONT BUMPER FOG LAMP C/W BRACKET RH <i>gap</i>	1	\$ 294.70	\$ 294.70
3	FRONT BUMPER FOG LAMP COVER GARNISH RH <i>gap</i>	1	\$ 121.30	\$ 121.30
4	FRONT BUMPER SIDE RETAINER <i>gap</i>	2	\$ 46.80	\$ 93.60
5	FRONT BUMPER SPONGE <i>gap</i>	1	\$ 217.60	\$ 217.60
6	FRONT BUMPER SIDE BEAM <i>gap</i>	2	\$ 97.90	\$ 195.80
7	FRONT BUMPER TOP RUBBER <i>gap</i>	1	\$ 69.40	\$ 69.40
8	BONNET <i>Defect</i>	1	\$ 1,385.00	\$ 1,385.00
9	BONNET LOCK <i>new</i>	1	\$ 129.90	\$ 129.90
10	BONNET HINGE <i>new</i>	2	\$ 49.10	\$ 98.20
11	BONNET INSULATOR <i>gap</i>	1	\$ 221.10	\$ 221.10
12	BONNET STOPPER <i>gap</i>	4	\$ 18.10	\$ 72.40
13	HEAD LAMP RH <i>cracked</i>	1	\$ 1,198.80	\$ 1,198.80
14	HEAD LAMP LOWER BRACKET <i>RH cracked</i>	2	\$ 89.60	\$ 179.20
15	HEADLAMP CLIP <i>gap</i>	4	\$ 26.70	\$ 106.80
16	HEADLAMP BOTTOM SUPPORT BRACKET <i>gap</i>	2	\$ 27.60	\$ 55.20
17	FRONT SUPPORT PANEL <i>new</i>	1	\$ 949.30	\$ 949.30
18	FRONT FENDER RH <i>distorted</i>	1	\$ 730.00	\$ 730.00
19	FRONT FENDER MUDFLAP RH <i>new</i>	1	\$ 165.00	\$ 165.00
20	FRONT FENDER COWLING RH <i>distorted</i>	1	\$ 178.00	\$ 178.00
21	FRONT DOOR VIEW MIRROR RH <i>new</i>	1	\$ 1,248.60	\$ 1,248.60

TO : INDIA INTERNATIONAL MOTOR CLAIMS DEPTS
 VEHICLE NO : SDS448U
 MODEL : HYUNDAI ELANTRA
 DATE OF ACCIDENT : 16.09.2024
 TIME OF ACCIDENT : 16:00 HOURS

22	FRONT FENDER TOP CORNER GARNISH RH	1	\$ 38.60	\$ 38.60
23	FRONT FENDER TOP INNER GARNISH RH	1	\$ 164.10	\$ 164.10

TOTAL PRICE \$ 8,711.00
 LESS 20% \$ 1,742.20
SUB TOTAL PRICE \$ 6,968.80

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTALS/NETT
1	FRONT BUMPER CLIP (SET)	1	\$ 80.00	\$ 80.00
2	CENTER GRILLE CLIP (SET)	1	\$ 50.00	\$ 50.00
3	BONNET INSULATOR CLIP	1	\$ 50.00	\$ 50.00
4	FRONT FENDER INNER COWLING CLIP (SET)	1	\$ 50.00	\$ 50.00
5	FRONT SUPPORT PANEL TOP COVER GARNISH (SET)	1	\$ 30.00	\$ 30.00
6	FRONT ENGINE UNDER COVER CLIP (SET)	1	\$ 50.00	\$ 50.00
7	RADIATOR COOLANT	1	\$ 60.00	\$ 60.00

TOTAL \$ 370.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	400
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	400
3	TUFF COAT	\$ 250.00	+
4	WIRING CHECK	\$ 250.00	30
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	+
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	+
7	REFOCUS HEADLAMP BEAM	\$ 60.00	+
8	REMOVE AND REFIX DASH BOARD AND INTERNAL WIRING	\$ 850.00	+

TO : INDIA INTERNATIONAL MOTOR CLAIMS DEPTS
VEHICLE NO : SDS448U
MODEL : HYUNDAI ELANTRA
DATE OF ACCIDENT : 16.09.2024
TIME OF ACCIDENT : 16:00 HOURS

9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	X
---	--	-----------	---

TOTAL \$ 4,560.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,338.80
TOTAL LABOUR COST : \$ 4,560.00
TOTAL REPAIR COST : \$ 11,898.80

Ashwin L
2/s 30/09/24
O.A. Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: