

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9 , Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 Anson Road
 #15-00 Springleaf Tower
 Singapore 079909

TEL: - FAX: -

ATTN: Motor Claim Department

Your Ref No: WEE GUAN ENG PL

Claim Type: Third Party

Accident Date: 13/09/2024

TP Veh Reg No: SLF7445E

Estimate No: ES1602239

Date: 13 Sep 2024

Policy No: V0103913

Veh Reg No: SGF7568T

Make/Model: TOYOTA VIOS 1.5E A

Chassis No: MR053HY4204183197

Engine No: 1NZX414247


Reg. Date: 21/04/2006

Estimate Repair Cost to Vehicle No :SGF7568T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 Front Bumper	1,800.00	1 PC	R 1,800.00 X 1,800.00	1,800.00
Net Price				
front 2 Number Plate	50.00	1 PC	40 50.00 40 s/n 50.00	50.00
Labour				
3 Labour to renew number plate .	30.00	1 -	30.00	
4 Labour to knock & renew front bumper .	800.00	1 -	800.00	120
5 To spray & painting front bumper .	600.00	1 -	600.00	200
6 To rust proofing on accident affected area .	380.00	1 -	380.00 X	
			1,810.00	1,810.00
			Total	S\$ 3,660.00
			Add GST @ 9%	295.20
			Total Amount Payable	S\$ 3,955.20

TOTAL: SINGAPORE DOLLAR THREE THOUSAND NINE HUNDRED FIFTY FIVE AND CENTS TWENTY ONLY

For HUP LIAN HUAT ENGINEERING WORKS



AUTHORISED SIGNATURE

Not Authorised
 Mr

Mela-s
 11/10/24

P/P #360/

2 days.

Wh p/h/Ata rpi