

# WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163  
Company Registration Number: 200505706E

## Quotation

DATE: 2/5/2024  
VEHICLE NO: PD596L  
DRIVER: TEO SENG HOW  
TYPE OF CLAIM: CLAIM 3 P  
PREPARED BY: KAMARUL

LOCATION: Gul Workshop  
Q REF No:  
DEPARTMENT: BUS (AIRPORT)  
ACCIDENT DATE: 11/4/2024  
REF NO: JW/0424/185

S/N	Description	Qty	Cost per Unit	Total cost W/O Gst
SPARE PARTS				
1	L/H/S TAIL LAMP <i>SLR ✓</i>	1	180	180.00
LABOUR				
1	REMOVE AND INSTALL NEW L/H/S TAIL LAMP	1	50	<del>50.00</del> <i>30</i>
2	REPAIR AND PANEL BEAT REAR BUMPER DENTED	1	280	<del>280.00</del> <i>250</i>
3	REPAIR AND PANEL BEAT L/H/S BOTTOM PANEL	1	150	<del>150.00</del> <i>80 X</i>
4	REPAIR AND PANEL BEAT L/H/S PANEL	1	180	<del>180.00</del>
5	REPAIR AND PANEL BEAT L/H/S CORNER PANEL	1	100	<del>100.00</del> <i>80</i>
SPRAY PAINTING				
1	PUTTY AND SPRAY PAINTING REAR BUMPER	1	350	<del>350.00</del> <i>250</i>
2	PUTTY AND SPRAY PAINTING L/H/S PANEL	1	200	<del>200.00</del>
Total Amount				1490.00

Total cost subjected to GST  
Remarks: LOU 03 DAYS

*[Signature]*  
Signature of Workshop

*[Signature]* 2/5/2024  
Signature of Department Head

\_\_\_\_\_  
Signature of Claim

Monday 24/06/24 @ 1400hrs (LKK.)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

*Ram*  
*Hy 900 10068*  
*3 days*  
*24/06/24*  
*Repair after repair*